

NUMBER OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
TRANSPORTER	OIL
	GAS
PERFORATION OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION
Santa Fe, New Mexico

MISCELLANEOUS NOTICES

strict Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Notice by Checking Below

NOTICE OF INTENTION TO CHANGE PLANS		NOTICE OF INTENTION TO TEMPORARILY ABANDON WELL		NOTICE OF INTENTION TO DRILL DEEPER	
NOTICE OF INTENTION TO PLUG WELL		NOTICE OF INTENTION TO PLUG BACK		NOTICE OF INTENTION TO SET LINER	X
NOTICE OF INTENTION TO SQUEEZE	X	NOTICE OF INTENTION TO ACIDIZE	X	NOTICE OF INTENTION TO SHOOT (Nitro)	
NOTICE OF INTENTION TO GUN PERFORATE	X	NOTICE OF INTENTION (OTHER) Sand oil frac	X	NOTICE OF INTENTION (OTHER)	

OIL CONSERVATION COMMISSION
SANTA FE, NEW MEXICO

Hobbs, New Mexico
(Place)

April 6, 1964
(Date)

Gentlemen:

Following is a Notice of Intention to do certain work as described below at the.....

Amerada Petroleum Corporation State "B" Well No. 1 in F
(Company or Operator) (Unit)
SE 1/4 NW 1/4 of Sec. 29, T. 18S, R. 38E, NMPM, Hobbs Pool
(40-acre Subdivision)
Lea County.

FULL DETAILS OF PROPOSED PLAN OF WORK
(FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS)

Pull rods, pump and tubing. Drill out cement in open hole from 4014' to original TD of 4214'. Run Gamma Ray Sonic Logs. Run and cement 4-1/2" Liner. Perforate 4-1/2" casing from log with 2 shots per foot from 4172' to 4182'. Run packer and swab test. Acidize with 500 gals. 15% NE acid. Swab test. If not commercial squeeze. Perforate 4-1/2" liner with 2 shots per foot from 4150' to 4161'. Run packer and swab test. Acidize with 500 gals. 15% NE acid. Swab test. If not commercial squeeze. Perforate 4-1/2" liner with 2 shots per foot from 4122' to 4141'. Run packer and swab test. Acidize with 500 gals. 15% NE acid. Swab test. If not commercial, squeeze. Perforate 4-1/2" liner with 2 shots per foot from 4098' to 4108'. Run packer and swab test. Acidize with 500 gals. 15% NE acid. If not commercial, squeeze. Perforate 4-1/2" liner with 2 shots per foot from 4019' to 4036'. Swab test. Acidize and sand oil frac. Swab test. Testing to be suspended when top allowable production is established.

Approved....., 19.....
Except as follows:

Approved
OIL CONSERVATION COMMISSION

By.....
Title.....

Amerada Petroleum Corporation
Company or Operator

By.....
Position..... District Superintendent
Send Communications regarding well to:

Name..... Amerada Petroleum Corporation
Address..... Box 668 - Hobbs, New Mexico

(Form C-102)
(Revised 7/1/62)
HOBBS OFFICE O. C. C.
APR 7 11 07 AM '64