## STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

we, or corice accrives		
POITRIBUTION	_	
SANTA FE		1
PILE	_	
U.S.G.S.	1	1
LAND OFFICE		1
OPERATOR	ı	1

## OIL CONSERVATION DIVISION

Form C-103 .

	P. O. BOX	2088	Revised 10-1-78
DISTRIBUTION			KC113C4 13 1 73
SANTA FE	SANTA FE, NEW N	MEXICO 87301	Sa. Indicate Type of Lease
FILE			
U.S.G.S.			State XX Fee
LAND OFFICE			5. State Oil & Gas Lease No.
OPERATOR	· ·		1
			mmmmmm.
61,100	V HOTICES AND DEPORTS ON V	WELLS	
SUNDRY NOTICES AND REPORTS ON WELLS  [DO NOT USE THIS FORM FOR PROPERTY OF THE			
(DO NOT USE "APPLICAT	ICH FOR PERMIT -" IFORM C-1011 FOR SUCH	PROPUSACS.7	7. Unit Agreement Name
			N. HOBBS (G/SA) UNIT
OIL X WELL WELL	OTHER-		8, Farm or Lease Name
2. Name of Operator			SECTION 29
SHELL OIL COMPANY			9. Well No.
Address of Operator			321
	N TEVAS 77001		
P. O. BOX 991, HOUSTO	Y. ILAMS TANDI		10. Field and Pool, or Wildcat
4. Location of Well	NORTH	1650	HOBBS (G/SA)
UNIT LETTERG	2310 FEET FROM THE NORTH	LINE AND 165U FEET FR	TITITITITI "
UNIT CELLER			
EAST	29 18-S	RANGE 38-E NMP	
THELINE, SECTI	ONTOWNSHIP		VIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII
	15. Elevation (Show whether I	DF RT GR. etc.)	12. County
		57, 107, 570,	
	3652' DF		LEA CILITITATION
lé. Chack	Appropriate Box To Indicate N	ature of Notice, Report of	Other Data
Check	Appropriate Dox 10 indicate is	attic of fronce, repende	NT REPORT OF:
NOTICE OF I	NTENTION TO:	30832902	ALL SILVERS
•		·	
	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
PERFORM REMEDIAL WORK	-	COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT
TEMPORARILY ABANDON	r		
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	
		OTHER	
DEEPEN AND ACIDI	7F X	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	
OTHER DELT EN AND ACTUI			
	Descripte (Clearly state all pertinent den	ails, and give pertinent dates, includ	ling estimated date of starting any propose
work) SEE RULE 1103.	Spergrisms (overs) trans-		
WOIN, JEE NOTE			
1. Clean out to 3950	) * + _		•
1. Otean out to osci	' <del>_</del> •		
	to a man ID of 4270! (Mayi	mum TD of 4309')	
2. Deepen well /2' 1	to a new TD of 4279' (Maxi	mum 10 01 4303 j.	
			1 1 1000# anadad
<ol><li>Acidize open hole</li></ol>	e using 6500 gals 15% HCl-	-NEA double inhibited a	icia and 1000# graded
rock salt as dive	rter		
TUCK Said as alve			•
		-11 to production	
4. Install production	on equipment and return we	ell to production.	
•			
	•		
	• •		
•			

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. TITLE SUPERVISOR REG. & PERMITTING DATE OCTOBER 19, 1983 PRIGINAL SIGNED BY JERRY SEXTON ···OCT 24 1983 DISTRICT I SUPERVISOR CONDITIONS OF APPROVAL, IF ANYI

MOBBS CITICE