DISTRIBUTION  SANTA FE  NEW MEXICO OIL CONSERVATION COMMISSION  Effective 1-1-65  FILE  U.S.G.S.  LAND OFFICE  OPERATOR  SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)  7. Unit Agreement Name  3. Name of Operator  America Potroloum Corporation  8. Farm or Lease Name  State BH  O Well No.			Supersedes Old
SUNDRY NOTICES AND REPORTS ON WELLS  SUNDRY NOTICES AND REPORTS ON WELLS  SUNDRY NOTICES AND REPORTS ON WELLS  OF SUNDRY NOTICES AND REPORTS ON WELLS  I. Lieu Mandauling Notices Make a sundry No	DISTRIBUTION	9 M 4 A THE 8.0	. C-102 and C-103
U.S. OBSECTION PROPERTY OF THE MANDER PROPERTY OF THE		<del>  </del>	
SUNDRY NOTICES AND REPORTS ON WELLS  DO NOT HAR FIRST PROTECTION OF A PROPERTY OF SHAPE AND PROPERTY OF SHAPE		Jul 17 11 24 AM	5a. Indicate Type of Lease
SUNDRY NOTICES AND REPORTS ON WELLS  SUNDRY NOTICES AND REPORTS ON WELLS  ON NOTICES AND REPORTS ON WELLS  ON NOTICES AND REPORTS ON WELLS  OF THE PROPERTY OF			State K Fee.
SUNDRY NOTICES AND REPORTS ON WELLS  OF THE STATE OF THE		<del>  </del>	_
And the control of th			A-1469
2. None of Operator  Americal Petreleus Corporation  1. Address of Operator  A. Do, Box 668 - Habbs, New Maxice  4. Location of Well  User Little C  29	SU (DO NOT USE THIS FORM FI USE "APP	INDRY NOTICES AND REPORTS ON WELLS  OR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. PLICATION FOR PERMIT _" (FORM C-101) FOR SUCH PROPOSALS.)	
Abstract Petrelous Corperation  3. Additions of Operative  4. Location of Well  Line, and from 190, pox 668 - Hebbs, New Markete  4. Location of Well  Line, and from 29		OTHER-	7. Unit Agreement Name
PLOS Box 668 - Hebbs, New Mexico  4. Location of Well  Unit Letter C 330 rear prom the North Line and 2310 rect from Rebbs  10. Field and Pool, or Wildow Rebbs  12. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Nortice of Intention "O:  FLUG AND ARABOON SUBSEQUENT REPORT OF:  PLUG AND ARABOON CHARGE PLANS COMMERCE OBILLING OPPOR ATTEMPORALITY ARABOON CHARGE PLANS COMMERCE OBILLING OPPOR CANGED TOTAL STRING CASING CHARGE PLANS COMMERCE OBILLING OPPOR CASING TOTAL STRING CASING CHARGE PLANS COMMERCE OBILLING OPPOR CASING TOTAL STRING CASING CHARGE PLANS COMMERCE OBILLING OPPOR CASING TOTAL STRING CASING CHARGE PLANS COMMERCE OBILLING OPPOR CASING TOTAL STRING CASING CHARGE PLANS COMMERCE OBILLING OPPOR CASING TOTAL STRING CASING CHARGE PLANS COMMERCE OBILLING OPPOR CASING TOTAL STRING CASING CHARGE PLANS COMMERCE OBILLING OPPOR CASING TOTAL STRING CASING CHARGE PLANS COMMERCE OBILLING OPPOR CASING TOTAL STRING CASING CHARGE PLANS COMMERCE OBILLING OPPOR CASING TOTAL STRING CASING CHARGE PLANS COMMERCE OBILLING OPPOR CASING TOTAL STRING CASING CHARGE PLANS COMMERCE OBILLING OPPOR CASING TOTAL STRING CASING CHARGE PLANS COMMERCE OBILLING OPPOR CASING TOTAL STRING CASING CHARGE PLANS COMMERCE OBILLING OPPOR CASING TOTAL STRING CASING CHARGE PLANS COMMERCE OBILLING OPPOR CASING TOTAL STRING CASING CHARGE PLANS COMMERCE OBILLING OPPOR CASING CHARGE PLANS COMMERCE PLANS COMMERCE OBILLING OPPOR CASING CHARGE PLANS COMMERCE PLANS COMMERCE OBILLING OPPOR CASING CHARGE PLANS COMMERCE OBILLING CASING CHARGE PLANS COMMERCE OBILLING CHARGE PLANS COMMERCE OBILLING CHARGE PLANS COMMERCE OBILLING CHARGE PLANS COMMERCE OBILLING CHARGE PLANS COMMERCE PLANS COMMERCE PLANS COMMERCE PLANS COMMERCE PLANS C	2. Name of Operator	releum Corperation	1 .
## West LINE, SECTION 29 TOWNSHIP 188 AANDE 38E NAME.    C	3. Address of Operator P.O. Box 66	8 - Hebbs, New Mexico	9. Well No.
Hebbs    Hebbs		•	10. Field and Pool, or Wildcat
15. Elevation (Show whether DF, RT, GR, etc.)  16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION "O:  PERSONN REMODIAL WORK  TEMPORALLY ARABOD  PULS AND ARABOD  PULS OF THE TOTAL WORK  TEMPORALLY ARABOD  PULS AND A	c	330 FEET FROM THE North LINE AND 2310 FEET FR	Hebbs
15. Elevation (Show whether DF, RT, CR, etc.)  3656 CB  Check Appropriate Box To Indicate Nature of Notice, Report or Other Data SUBSEQUENT REPORT OF:  PERFORM MEMBERIAL WORK  TEMPORALITY ABARDON  PULC ON ALTER CASING  OTHER  COMMENCE OF INTENTION TO:  PLUG AND ABARDON   REMEDIAL WORK  COMMENCE OF INTENTION TO:  PLUG AND ABARDON   REMEDIAL WORK  COMMENCE OF INTENTION TO:  CHANGE PLANS  OTHER String shot & acidise  IV. Describe Proposed of Completes Operations (Clearly state all pertinent details, and give pertinent dates, taclading estimated date of starting any proposed work) SEE RULE 1103.  Palled reds, pramp and tubing. String shet epen hele from 3248 to 4253 with 300 grains and 500 grains per foot of may respectively. Ran tubing and acidized epen hele 4228 to 4253 with 1000 gals. 15% NE acid. Ran rods & pump and resumed preduction,  No change in well status.  18.1 hereby certify that the information above is true and complete to the best of my knowledge and belief.  NOTE Matrict Superintendent  OATE 7-14-67	Voca		
16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:  PERFORM NEMEDIAL WORK  PLUS AND ABANDON  PULL OR ALTER CASING  OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1 103.  Pulled rods, pump and tubing. String shet epen hele from 3248 to 4253 with 300 grains and 500 grains per foot of pay respectively. Ran tubing and acidized epen hele 4228 to 4253 with 1000 gals. 15% NE acid. Ran rods & pump and restand preduction.  No change in well status.  Matrict Superintendent  DATE  PARE  Matrict Superintendent  DATE  7-14-57	THE LINE,	SECTION TOWNSHIP RANGE	<u> </u>
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  NOTICE OF INTENTION TO:  PERFORM NEMEDIAL WORK  TEMPORABLY ARANDON  PULC AND ADARDON  PULC AND ADARDON  TEMPORABLY ARANDON  PULC AND ADARDON  CHANCE PLANS  CHANCE CASING  PLUC AND ADARDON  PAUL CHANCE CASING  PLUC AND ADARDON  CHANCE PLANS  CHANCE PLANS  CHANCE CASING  CHANCE PLANS  CHANCE CASING  CHANCE PLANS  CHANCE CRITICE CASING  CHANCE PLANS  CHANGE PLANS  CHANCE PLANS			
NOTICE OF INTENTION TO:  PERFORM SEMBSIAL WORK  TEMPORABILY ABANDON  PULL OR ALTER CASING  OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE ROLE 1105.  Pulled rods, prains and 500 grains per foot of pay respectively. Ran tubing and acidized epen hele 4228 to 4253 with 1000 gals. 15% NE acid. Ran rods & pump and restriction.  No change in well status.  District Superintendent  DATE  NETEROR CASING  ALTERING CASING  PLUG AND ABANDONNER!  COMMENCE DRILLING OPHS.  ALTERING CASING  COMENCE DRILLING OPHS.  ALTERING CASING  COMMENCE DR			Other Data
PERFORM REMODAL WORK  PULS AND ABANDON  PULS AND ABANDON  PULS OF ALTER CASING  OTHER String shot & acidise  IT. Describe frepessed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) see RULE 1103.  Pulled rods, pamp and tubing. String shot epen hele from 3248' to 4253' with  300 grains and 500 grains per foot of pay respectively. Ran tubing and acidized epen hele 4228' to 4253' with 1000 gals. 15% NE acid. Ran rods & pump and resumed preduction.  No change in well status.  18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.  District Superintendent  DATE  PLUS AND ABANDONMENT  ABANDONMENT  PLUS AND ABANDONMENT  ABANDONMENT  PLUS AND ABANDONMENT  ABANDON  PRINC CASING  PRIN			
PLUG AND ABANDONMENT  TITLE Mistrict Superintendent  Commence of Illeing Opins.  PLUG AND ABANDONMENT  PLUG AND ABANDONMENT  PLUG AND ABANDONMENT  PLUG AND ABANDONMENT  CASING TEST AND CEMENT JOB  OTHER  CASING TEST AND CEMENT JOB  OTHER String shot & acidise  Including estimated date of starting any proposed work) see RULE 1703.  Palled rods, pump and tubing. String shot epen hele from 3248 to 4253 with  300 grains and 500 grains per foot of pay respectively. Ran tubing and acidized epen hole 4228 to 4253 with 1000 gals. 15% NE acid. Ran rods & pump and resumed production.  No change in well status.  Is thereby certify that the information above is true and complete to the best of my knowledge and belief.  DATE 7-14-67	NOTICE	SF INTENTION . C.	
TEMPORARILY ASANDON PULL OR ALTER CASING  OTHER  OTHER  TY, Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) see role 103.  Pulled rods, pump and tubing. String shot epen hele from 3248 to 4253 with 300 grains and 500 grains per foot of pay respectively. Ran tubing and soldized epen hele 4228 to 4253 with 1000 gals. 15% NE acid. Ran rods & pump and resumed production.  No change in well status.  18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.  DATE  Mistrict Superintendent  DATE  PULL AND ABANDONMENT  TITLE Mistrict Superintendent  DATE  PATE	PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
OTHER String shot & acidise  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 103.  Pulled reds, pump and tubing. String shot open hole from 3248 to 4253 with 300 grains and 500 grains per foot of pay respectively. Ran tubing and acidized open hole 4228 to 4253 with 1000 gals. 15% NE acid. Ran rods & pump and resumed production.  No change in well status.  18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.  SIGNED B. J.	i i i i i i i i i i i i i i i i i i i	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  Pulled rods, pump and tubing. String shot open hole from 3248 to 4253 with 300 grains and 500 grains per foot of pay respectively. Ran tubing and acidized open hole 4228 to 4253 with 1000 gals. 15% NE acid. Ran rods & pump and resumed production.  No change in well status.  18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.  District Superintendent  DATE 7-14-57	PULL OR ALTER CASING	——————————————————————————————————————	
Palled rods, pump and tubing. String shet epen hele from 3248 to 4253 with 300 grains and 500 grains per foot of pay respectively. Ran tubing and acidized epen hele 4253 with 1000 gals. 15% MR acid. Ran rods & pump and resumed production.  No change in well status.  18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.  District Superintendent  DATE 7-14-67		other String shot & s	<u>L</u>
Pulled rods, pump and tubing. String shot open hole from 3248 to 4253 with 300 grains and 500 grains per foot of pay respectively. Ran tubing and acidized open hole 4228 to 4253 with 1000 gals. 15% NE acid. Ran rods & pump and resumed production.  No change in well status.  18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.  Title District Superintendent DATE 7-14-67	OTHER		
B. A. B. District Superintendent DATE 7-14-67	300 grains an epen hele 422 resumed predu	ed 500 grains per foot of pay respectively. Ran to 28° to 4253° with 1000 gals. 15% NE acid. Ran rodu action.	abing and acidized
DATE		well status.	
DATE	18. I hereby certify that the info		
APPROVED BY	18. I hereby certify that the infor	rmation above is true and complete to the best of my knowledge and belief.	
APPROVED BY DATE	18. I hereby certify that the info	rmation above is true and complete to the best of my knowledge and belief.	DATE 7-14-67
	18. I hereby certify that the infor	mation above is true and complete to the best of my knowledge and belief.  TITLE District Superintendent	