

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State ☒ Fee ☐
5. State Oil & Gas Lease No. <u>B-2657</u>
7. Unit Agreement Name
8. Farm or Lease Name <u>STATE A-29</u>
9. Well No. <u>6</u>
10. Field and Pool, or Wildcat <u>Barra 7 Pines @ 10.0</u>
12. County <u>LEA</u>

SUNDY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER- ☐

2. Name of Operator
Continental Oil Company

3. Address of Operator
Box 460, Hobbs, New Mexico

4. Location of Well
UNIT LETTER N 660 FEET FROM THE SOUTH LINE AND 1980 FEET FROM
THE WEST LINE, SECTION 29 TOWNSHIP 18-S RANGE 38-E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)
NA

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is proposed to plug & abandon this well by the following procedures.

Spot a 25 sx cmt plug at TD (3172') to cover perms from 3158' to 3166'. Fill well with 10# mud and place a 10 sx cmt plug at surface. Cap well with dry hole marker and restore location

NMOC - 3

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Administrative Section Chief DATE 12-2-70

APPROVED BY [Signature] TITLE SUPV DATE DEC 4 1970

CONDITIONS OF APPROVAL, IF ANY: