

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-07443
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Lease Name or Unit Agreement Name State 1-29
2. Name of Operator Chevron U.S.A. Inc.	8. Well No. 2
3. Address of Operator P.O. Box 670, Hobbs, NM 88240	9. Pool name or Wildcat Budd's Seven Rivers
4. Well Location Unit Letter 0 : 990 Feet From The South Line and 1650 Feet From The East Line Section 29 Township 18S Range 38E NMPM Lea County	10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

SPOT 35' CMT ON CIBP @ 3060', CIRC WELLBORE W/ P&A MUD, PERF 7" @ 2852' SET
CICR @ 2752' SQZ W/ 50 SXS, CAP CICR W/ 25' CMT. PERF 7" & 9 5/8 @ 1500'
SET CICR @ 1400' SQZ W/ 200 SXS. ATTEMPT TO CIRC CMT TO SURFACE VIA 9 5/8" X 13 3/8".
NOTE 7" X 9 5/8" WAS BRADEN HEAD SQZ 'D W/ 528 SXS. THEREFORE, NO CMT CAN BE
BROUGHT UP 7" X 9 5/8. IF WE DO NOT CIRC CMT VIA 9 5/8 X 13 3/8 PERF BOTH 7" &
9 5/8" @ 292' AND CIRC CMT TO SURF. LEAVE 7" FULL OF CMT, CUTOFF WELLHEAD 3' BELOW
GL, REMOVE ANCHORS, CHANGE STATUS TO P&A.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Richard C. Kautz TITLE Staff Drilling Engineer DATE 11-08-89

TYPE OR PRINT NAME

Orig. Signed by
Paul Kautz
Geologist

TELEPHONE NO.

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE NOV 14 1989

CONDITIONS OF APPROVAL, IF ANY:

THE COMMISSION MUST BE NOTIFIED 24
HOURS PRIOR TO THE BEGINNING OF
PLUGGING OPERATIONS FOR THE C-103
TO BE APPROVED.

NOV 14 1989