I

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land	Offic	e]	AS	Crn	808			
Lease	No.	03	2233	-A				
Unit	B.	A.	Bou	ers	A			
		(Federal)						

SUNDRY NOTICES A	AND REPOR	TS ON	WELLS	
NOTICE OF INTENTION TO DRILL			UT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS			OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPO		CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	1 1		NG OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	ii		#ENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	7			! 1
NOTICE OF INTENTION TO ABANDON WELL.				
(INDICATE ABOVE BY CHECK MAR	RK NATURE OF REPORT, NO	TICE, OR OTHER D.	ATA)	
		Ja	mery 5	, 19. 56
Well No. 7 is located 2970 ft. fro	m S line and	330 (t. from	$negin{pmatrix} oldsymbol{\mathbb{E}} \ oldsymbol{\mathbb{W}} \end{bmatrix}$ line of s	ec. 29
W 1/4 of NW 1/4 of Sec 29 18-S (½ Sec. and Sec. No.) (Twp.)	38-8 (Range)	(Meridian)		
Bovers (Field) (Count	Loa		w Mexico State or Territory)	
(Field) (Count	y or Subdivision)	,	delice of Territory,	
(State names of and expected depths to objective sands; show ing points, and a l. Set a cast iron bridge plug in 2. Dump 10 feet of cement on top of 3. Fill casing with a mid laden flug. Place a 10-foot cement plug in 5. Place marker over well as required. Note: Current interval open to pro-	the 7-inch casif plug. nid. top of the 7-inch red by the New	llews: ng at 3090 ch casing. Mexico 011	feet. Conservati	on Commissio
I understand that this plan of work must receive approve Company Humble Oil & Refining Com	pany			
Address Bex 2347		Ma Par	Wood	
Hobbs	By	1 161 6000	6600	
You Veries	Titl	e	Agent	

U. S. GOVERNMENT PRINTING OFFICE 16-8437-5