

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-75

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-121) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

7. Unit Agreement Name
N. HOBBS (G/SA) UNIT

8. Form or Lease Name
SECTION 30

9. Well No.
221

10. Field and Pool, or Widened
HOBBS (G/SA)

UNIT LETTER F 2310 FEET FROM THE NORTH LINE AND 2310 FEET FROM
THE WEST LINE, SECTION 30 TOWNSHIP 18-S RANGE 38-E N.M.P.M.

15. Elevation (Show whether DF, RT, GR, etc.)
3659' GR

12. County
LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

OTHER PB, OAP & ACDZ ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPER. ☐
CASING TEST AND CEMENT JOB ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

OTHER ☐

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. POH w/prod equip.
2. CO to 4279' (TD).
3. PB to 4260' w/sd & hydromite.
4. Perf San Andres 4145'-94' (2 JSPF).
5. Acdz perms 4145' - 4205' & OH 4208'-60' w/4000 gals 15% HCl + 1500# rock salt.
6. Install prod equip & return well to prod.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

BY A. J. FORE

TITLE SUPERVISOR REG. & PERMITTING

DATE 3-03-88

ORIGINAL SIGNED BY JERRY SEATON
DISTRICT SUPERVISOR

PROVED BY

TITLE

DATE MAR 9 - 1988

15-11-1982

1000 1000 1988

UCD
HOBBS OFFICE