

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-75

5a. Indicate Type of Lease	
State ☐	Fee ☒
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒	GAS WELL ☐	OTHER ☐
Name of Operator SHELL WESTERN E&P INC.		
Address of Operator P. O. BOX 576, HOUSTON, TEXAS 77001 (WCK 4435)		
Location of Well UNIT LETTER <u>G</u> <u>2310</u> FEET FROM THE <u>NORTH</u> LINE AND <u>2310</u> FEET FROM THE <u>EAST</u> LINE, SECTION <u>30</u> TOWNSHIP <u>18-S</u> RANGE <u>38-E</u> N.M.P.M.		

7. Unit Agreement Name N. HOBBS (G/SA) UNIT
8. Farm or Lease Name SECTION 30
9. Well No. 321
10. Field and Pool, or Whistler HOBBS (G/SA)

11. Elevation (Show whether DF, RT, GR, etc.) 3654' GR	12. County LEA
---	-------------------

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐
PULL OR ALTER CASING ☐	OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐	ALTERING CASING ☐
COMMENCE DRILLING OPER. ☐	PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐	OTHER ☒ ACID DUMP

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-12-84: Pmpd 1000 gals 15% HCl-NEA dwn annulus & flushed w/100 bbls prod wtr. SI 1 hr.
Returned well to prod.

I, hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE 3-03-88

ORIGINAL SIGNED BY ERRY BENSON

APPROVED BY DISTRICT SUPERVISOR TITLE DATE