

(November 1983)  
(Formerly 9-331)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

Submit in triplicate  
(Other instructions on re-  
verse side)

Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

LC 032233 (a)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL ☒ GAS ☐  
WELL WELL OTHER

2. NAME OF OPERATOR

SHELL WESTERN E&P INC. (4431 WCK)

3. ADDRESS OF OPERATOR

P. O. BOX 576, HOUSTON, TEXAS 77001

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface

UNIT LETTER J, 2335' FSL & 2310' FEL

14. ~~XXXXXX~~ API NO.

30-025-07472

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3654' DF

7. UNIT AGREEMENT NAME

N. HOBBS (G/SA) UNIT

8. FARM OR LEASE NAME

SECTION 30

9. WELL NO.

331

10. FIELD AND POOL, OR WILDCAT

HOBBS (G/SA)

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

SEC. 30, T. 18-S, R. 38-E

12. COUNTY OR PARISH

LEA

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐

PULL OR ALTER CASING

☐

FRACTURE TREAT

☐

MULTIPLE COMPLETE

☐

SHOOT OR ACIDIZE

☐

ABANDON\*

☐

REPAIR WELL

☐

CHANGE PLANS

☐

(Other)

OAP & AT

☒

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐

REPAIRING WELL

☐

FRACTURE TREATMENT

☐

ALTERING CASING

☐

SHOOTING OR ACIDIZING

☐

ABANDONMENT\*

☐

(Other)

(Note: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any  
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-  
nent to this work.) \*

1) POOH w/ prod equip.

2) CO to 4225'.

3) Perf Grayburg/San Andres 4040' - 4052' w/ 2JSPF.

4) AT San Andres 4118' - 4225' w/ 1500 gals 15% HCl acid + 1000# rock salt.

5) AT Grayburg/San Andres 4014' - 4052' w/ 750 gals 15% HCl acid + 400# rock salt,  
using RBP and pkr.

6) RIH w/ prod equip and return well to production.

18. I hereby certify that the foregoing is true and correct

SIGNED

*W.F.N. Kelldore*

W.F.N. KELLDORE

TITLE

STAFF PRODUCTION ENGINEER

DATE

3/15/89

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

3-28-89

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the  
United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.