

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instructions on re-
verse side)

Budget Bureau No. 1-04-
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

LC 032233 (a)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

SHELL WESTERN E&P INC.

3. ADDRESS OF OPERATOR

P. O. BOX 576, HOUSTON, TEXAS 77001 (WCK 4435)

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

UNIT LTR P, 330' FSL & 330' FEL

7. UNIT AGREEMENT NAME

N. HOBBS (G/SA) UNIT

8. FARM OR LEASE NAME

SECTION 30

9. WELL NO.

441

10. FIELD AND POOL, OR WILDCAT

HOBBS (G/SA)

11. SEC. T. R. M. OR BLM. AND
SURVEY OR AREA

SEC. 30, T18S-R38E

12. COUNTY OR PARISH 13. STATE

LEA

NM

14. XXXXXXXX API NO.
30-025-07473

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3646' DF

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☐
☐

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☒
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

LOG & RAN 5-1/2" LNR ☒

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

12-18-86: Pulled prod equip. Tagged btm @ 4220'. Ran capacitance survey, temp survey & a GR log. Made crossflow checks 3965' - 4190'.

12-19-86: Logged w/caliper from 4220' - 3800'.

12-22-86: Deepened well to 4277'.

12-23 to 12-24-86: Ran caliper log from 4278' - 3800' (1st run) & 4277' - 3800' (2nd run).

12-25-86: Tagged btm @ 4276'. Ran 5-1/2" lnr to 4267'. Could not get lnr pass 4267'. Pmnd 300 BPW & could not get circ. Set lnr. TOL @ 3847', LC & float @ 4224' & guide shoe @ 4257'. Cmt'd lnr w/50 sx CIs "C" cmt + 13% Halad-9 + .4% CFR-2 + 3#/sx gilsonite + 1/2#/sx floccle + 2% CaCl2.

12-29-86: CO to TOL @ 3847'. Pres tstd TOL to 500# for 15 min, held OK. Tagged TOC @ 4197'. DO cmt to FC @ 4224'. Pres tstd lnr to 500#, held OK. Ran CBL/CCL log from PBTD to TOL.

(CONTINUED ON REVERSE SIDE)

18. I hereby certify that the foregoing is true and correct

SIGNED A. J. FORE

TITLE SUPERVISOR REG. & PERMITS

DATE JANUARY 15, 1987

(This space for Federal or State office use)

ACCEPTED FOR RECORD

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____

JAN 23 1987

*See Instructions on Reverse Side

CARLSBAD, NEW MEXICO