

November 1983)
Formerly 9-331)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIP
(Other instructions
reverse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME N. HOBBS (G/SA) UNIT
2. NAME OF OPERATOR SHELL WESTERN E&P INC.	8. FARM OR LEASE NAME SECTION 30
3. ADDRESS OF OPERATOR P. O. BOX 991, HOUSTON, TX 77001	9. WELL NO. 431
4. LOCATION OF WELL (Report location clearly and in accordance with any well requirements. See also space 17 below.) At surface UNIT LETTER I, 2310' PSL, 990' PSL	10. FIELD AND POOL, OR WILDCAT HOBBS (G/SA)
11. PERMIT NO. N/A	11. SEC., T., R., M., OR BLK. AND SECTION 30, T-18-S, R-38-E
12. ELEVATION (Spot, shoulder, etc., etc.) 3652' OF	12. COUNTY OR PARISH LEA
	13. STATE NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	☒	PULL OR ALTER CASING	☐
FRACURE TREAT	☐	MULTIPLE COMPLET	☐
SHOOT OR ACIDIZE	☒	ABANDON*	☐
REPAIR WELL	☐	CHANGE PLUGS	☐
(Other)	☐	& DEEPEN	☒

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	☐	REPAIRING WELL	☐
FRACURE TREATMENT	☐	ALTERING CASING	☐
SHOOTING OR ACIDIZING	☐	ABANDONMENT*	☐
(Other)	☐		

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS. Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. Retrieve Lynes Inflata-Plug @ 4000'.
2. Spot sand to 4103' with approximately 2800# sand.
3. Set 5-1/2" FBRC @ 3900'±.
4. Squeeze Zone I perforations 3875'-4060' w/1500 gals flochek and 75 sx Class "C" 50/50 Pozmix containing 2% Cal12. WOC 24 hrs.
5. Drill out cement and clean out to TD 4218'. Pressure test squeeze to 500 psi. Deepen well to 4266'.
6. Acidize Zone II and III using 1500 gals 15% HCl-NEA.
7. Install production equipment and return well to production.

18. I hereby certify that the foregoing is true and correct

SIGNED *A. J. FORE* A. J. FORE

SUPV. REG. & PERMITTING

DATE APRIL 12, 1984

(This space for Federal or State office use)

APPROVED *A. J. FORE*

TITLE

CONDITIONS OF APPROVAL, IF ANY:

DATE 12-14-84

*See Instructions on Reverse Side

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.