

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN DUPLICATE
With instructions on backForm approved,
Budget Function No. 42-10102

SUNDAY NOTICE AND REPORTS ON WELLS

(Do not use this form for purposes to drill or plug back to a different reservoir.
Use APPLICATION FOR PERMIT TO DRILL OR PLUG (Forms 5-11 and 5-12))

5. LEASE DESIGNATION AND SERIAL NO.

AC 10102 10

6. IF INDIAN, NAME OF THE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Bowers A. Federal

9. WELL NO.

6

10. FIELD AND POOL, OR WILDCAT

Bowers A. Rivers

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

S30, T18S, R38E

12. COUNTY OR PARISH

Lea

13. STATE

N Mex

1. OIL ☒ GAS ☐
WELL ☒ WELL ☐ OTHER

2. NAME OF OPERATOR

Humble Oil & Refg Co

3. ADDRESS OF OPERATOR

Box 1600, Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface1310 FSL
330 FSL, 330 FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether OF, RT, GR, etc.)

3656' OF

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Test Form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)

We propose to plug and abandon well as follows:

1. Set cement plug from 2950-3190' TO w 50 sax.
2. Salvage approx 2550' 7" csg.
3. Spot 50 sax across cut above.
4. Set cement plug from 35' to Surface w 10 sax
5. Install dry hole marker & clean Location.
6. Mud laden fluid between plugs.

AGREEMENT:

Set additional 20-sack plug at 1400-1500 feet.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Unit Head

DATE

3/4/70

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED
MAR 11 1970
ARTHUR R. BROWN
DISTRICT ENGINEER

*See Instructions on Reverse Side