## Submit 3 Copies to Appropriate District Office

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVAT		WELL API NO.	
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mex	ico 87504-2088	5. Indicate Type of Lease STATE	FEE X
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No.	
( DO NOT USE THIS FORM FOR PRO DIFFERENT RESER	CES AND REPORTS ON VIPOSALS TO DRILL OR TO DEE VOIR. USE "APPLICATION FOR 101) FOR SUCH PROPOSALS.)	PEN OR PLUG BACK TO A	7. Lease Name or Unit Agreeme	nt Name
1. Type of Well: OIL CAS WELL X WELL	OTHER		N. HOBBS (G/SA)   SECTION 31	UNIT
2. Name of Operator			8. Well No. 211	
SHELL WESTERN E&P IN  3. Address of Operator	<u>C.</u>		9. Pool name or Wildcat	
P. 0. BOX 576, HOUST	ON. TX 77001 (WC	K 4435)	HOBBS (G/SA)	
4. Well Location  Unit Letter C :440			10 Feet From The W	EST Line
Section 31	Township 18S	Range 38E	nmpm LEA	County
	10. Elevation (Show who	esher DF, RKB, RT, GR, etc.)		
11. Check A NOTICE OF INT	Appropriate Box to Indicate ENTION TO:		eport, or Other Data SEQUENT REPORT	OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING	CASING
TEMPORARILY ABANDON	CHANGE PLANS [	COMMENCE DRILLING	OPNS. PLUG AND	ABANDONMENT [
PULL OR ALTER CASING		CASING TEST AND CE	EMENT JOB	
OTHER: Set CIBP, MAP \$	Acdz	OTHER:		
12. Describe Proposed or Completed Operation work) SEE RULE 1103.  1. POH w/prod equipment of the control of th	φ. 40'. 1 Andres 4106'-3	2' /2 JSPF).	·	oroposed
I hereby certify that the information above is tru			UDV -	E 22.60
SKINATURE SHIPMIT	reman	_ TITLE REGULATURY S	UPV. DATE	5-66-01
TYPEORPRINTNAME J. H. SMIT	HERMAN	(7	13) 870-3797 телетно	NE NO.
DISTRICT (	BY JERRY SEXTON SUPERVISOR	TILE	. M	AY 2 5 1989
APPROVED BY				