

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State ☐	Fee ☒
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator

SHELL WESTERN E&P INC.

Address of Operator

P. O. BOX 576, HOUSTON, TEXAS 77001 (WCK 4435)

Location of Well

UNIT LETTER K 2310 FEET FROM THE WEST LINE AND 2196 FEET FROM
THE SOUTH LINE, SECTION 31 TOWNSHIP 18S RANGE 38E NMPM.

7. Unit Agreement Name

N. HOBBS (G/SA) UNIT

8. Farm or Lease Name

SECTION 31

9. Well No.

231

10. Field and Pool, or Wildcat

HOBBS (G/SA)

15. Elevation (Show whether DF, RT, GR, etc.)

3644' GR

12. County

LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐

CHANGE PLANS ☐

OTHER DO CIBP TO OAP ☒

REMEDIATION WORK ☐

COMMENCE DRILLING OPERATIONS ☐

CASING TEST AND CEMENT JOB ☐

OTHER ☐

ALTERING CASING ☐

PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. POH w/prod equip.
2. DO CIBP @ 4126'.
3. CO to TD (4190').
4. Install prod equip & return well to prod.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J. Marcus Winder for A. J. FORE

TITLE SUPERVISOR REG. & PERMITTING

DATE 3-31-88

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT 1 SUPERVISOR

TITLE

DATE APR 5 1988