

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes OH
C-102 and C-101
Effective 1-1-75

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR NOTICES TO PRODUCE OR TO ABANDON A WELL IN A DIFFERENT RESERVOIR.
USE FORM C-102 FOR SUCH REPORTS.)

1. **Oil Well** ☒ **Gas Well** ☐ **Other** _____

2. **Name of Operator**
Sun Oil Company

3. **Address of Operator**
P. O. Box 1861, Midland, TX 79702

4. **Location of Well**
UNIT LETTER E 1650 FEET FROM THE North LINE AND 990 FEET FROM
THE West LINE, SECTION 31 TOWNSHIP 18S RANGE 38E

5. **Elevation (Show whether DF, LT, CR, etc.)**
3254 DF

5a. **Indicate Type of Lease**
State ☐ Free ☒

5. **State Oil & Gas Lease No.**

6. **Form of Lease**
Clara Fowler

7. **Well No.**
3

8. **Field (or Loc.) of Well**
Bowers

9. **County**
Lea

16. **Check Appropriate Box To Indicate Nature of Notice, Report or Other Data**

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPER. ☐	PLUG AND ABANDONMENT ☒
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	
		OTHER _____	

17. **Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.**

8-11-76 MIRU. Set Anchors

8-12 Pull rods & tbg. Set CIBP @ 3100'. Place 3 sx cmt on plug w/dump bailer (3100-3065)

8-13 Tag top cmt. w/tbg @ 3063. Displace hole w/75 bbls. Mud. Sptd 20 sx cmt 1730-1600, Sptd 75 sx 150-Surface. Cut off wellhead, weld on plate, install permanent marker/

18. **I hereby certify that the information above is true and complete to the best of my knowledge and belief.**

SIGNED Quinn Muntzel TITLE Production Staff Associate DATE 2-20-79

APPROVED BY Jerry Sexton TITLE _____ DATE FEB 26 1979

CONDITIONS OF APPROVAL, IF ANY: Dist. L. Supv.