

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name N. HOBBS (G/SA) UNIT	
2. Name of Operator SHELL WESTERN E&P INC.		8. Farm or Lease Name SECTION 32	
3. Address of Operator P. O. BOX 991, HOUSTON, TEXAS 77001		9. Well No. 411	
4. Location of Well UNIT LETTER <u>A</u> <u>330</u> FEET FROM THE <u>NORTH</u> LINE AND <u>330</u> FEET FROM THE <u>EAST</u> LINE, SECTION <u>32</u> TOWNSHIP <u>18-S</u> RANGE <u>38-E</u> NMPM.		10. Field and Pool, or Wildcat HOBBS (G/SA)	
15. Elevation (Show whether DF, RT, GR, etc.) 3658' DF		12. County LEA	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <u>DEEPENED AND ACIDIZED</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-17-84: Cleaned out to 3800'. Started drilling at 4100' to 4160'.

2-20 to 2-22-84: Drilled new 6-1/4" open hole to 4272' (new TD). Acidized open hole interval 4055' to 4272' with 7500 gals 15% HCl-NEA and 2000# graded rock salt.

2-23-84: Installed production equipment and returned well to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J. Curtis for A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE MARCH 15, 1984

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT SUPERVISOR

TITLE _____

DATE MAR 20 1984

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
MAR 19 1984
C. C.
HOBBS OFFICE