

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-73

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

CIL WELL ☒ GAS WELL ☐ OTHER ☐
Name of Operator
SHELL WESTERN E&P INC.
Address of Operator
P. O. BOX 576, HOUSTON, TEXAS 77001 (WCK 4435)
Location of Well
UNIT LETTER G 2310 FEET FROM THE NORTH LINE AND 2310 FEET FROM
THE EAST LINE, SECTION 32 TOWNSHIP 18S RANGE 38E N.M.P.M.

7. Unit Agreement Name
N. HOBBS (G/SA) UNIT
8. Farm or Lease Name
SECTION 32
9. Well No.
322
10. Field and Pool, or Widened
HOBBS (G/SA)

15. Elevation (Show whether DF, RT, GR, etc.)
3637' GR
12. County
LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	

OTHER PB for WSO ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-12 to 10-16-87:

POH w/prod equip. Tagged btm @ 4237'. PB to 4220' w/sd.
PB to 4170' w/Cal-Seal. Knocked out bridges @ 4170' & 4175'.
Shoved to lnr shoe @ 4217'. Dmpd 4 SX cmt. Tagged btm @
4205'. Installed prod equip & ret'd well to prod.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

APPROVED BY A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE 7-19-88

APPROVED BY _____ TITLE _____ DATE _____