

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-07522
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
Chevron U.S.A. Inc.

3. Address of Operator
P.O. Box 670, Hobbs, NM 88240

4. Well Location
Unit Letter C : 330 Feet From The North Line and 2310 Feet From The West Line
Section 32 Township 18S Range 38E NMPM Lea County

7. Lease Name or Unit Agreement Name

W.D. Grimes NCT-A

8. Well No. 4

9. Pool name or Wildcat
Powers Seven Rivers

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

CAP CIBP @ 3078' W/ 35' CMT, CIRC WELLBORE W/ P&A MUD. PERF 7" CSG @ 2792' SET CIRC @ 2692' SQZ 9 5/8" SHOE W/ 50 SXS CMT CAP CIRC W/ 25' CMT. SPOT 200' BALANCED CMT PLUG F 1300 to 1100' W/ 40 SXS. PERF 7" & 9 5/8" @ 270' SQZ PERFS & ATTEMPT TO CIRC CMT TO SURFACE VIA 9 5/8" X 15 1/2" ANNULUS WITH 200 SXS. * RECORDS ARE NOT CLEAR AS TO WHETHER THIS INTERVAL HAS BEEN CMT'D. IF ABLE TO CIRC CMT TO SURFACE, CLOSE IN VALVE & SQUEEZE 15 1/2" SHOE & LEAVE 7" CSG FULL OF CMT. CUT OFF WELLHEAD 3' BELOW GL. REMOVE ANCHORS, CHANGE STATUS TO P&A.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Richard R. H. TITLE Div. Dir. G. Mgr. DATE 11-08-89

TYPE OR PRINT NAME _____ TELEPHONE NO. _____

(This space for State Use)

APPROVED BY _____ Orig. Signed by Paul Kautz TITLE _____ DATE _____
Geologist

CONDITIONS OF APPROVAL, IF ANY:

NOV 14 1989

THE COMMISSION MUST BE NOTIFIED 24
HOURS PRIOR TO THE BEGINNING OF
DRILLING OPERATIONS FOR THE WELL.