

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT TO DRILL" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name N. HOBBS (G/SA) UNIT
2. Name of Operator SHELL OIL COMPANY	8. Farm or Lease Name SECTION 32
3. Address of Operator P. O. BOX 991, HOUSTON, TX 77001	9. Well No. 241
4. Location of Well UNIT LETTER N 990 FEET FROM THE SOUTH LINE AND 2310 FEET FROM THE WEST LINE, SECTION 32 TOWNSHIP 18-S RANGE 38-E N.M.P.M.	10. Field and Pool, or Wildcat HOBBS (G/SA)
11. Elevation (Show whether DF, RT, GR, etc.) 3638' GR	12. County LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER WATER SHUT-OFF <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-12-83: Perf'd 4 squeeze holes @ 4046'.
4-15-83: Set 7" Baker Model "K" CICR @ 3936'.
4-20-83 to 4-22-83: Pumped 50 sx Class "C" cmt + 2% CaCl₂. WOC 24 hrs. Tagged cmt @ 3921'.
Drld out CICR @ 3936' and cmt to 4138'. Pressure test to 500# - held OK.
4-25-83 to 4-27-83: Drld 4138' to 4194'. Cleaned out to 4266'. Installed production equipment and returned well to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Eddie Seay A. J. FORE

TITLE SUPERVISOR REG. & PERMITTING

DATE MAY 12, 1983

ORIGINAL SIGNED BY EDDIE SEAY
OIL & GAS INSPECTOR

APPROVED BY _____

TITLE _____

DATE MAY 16 1983

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
MAY 16 1983
O.C.D.
HOBBS OFFICE