

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease  
State ☒ Fee ☐

5. State Oil & Gas Lease No.  
B-2656

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator <u>Continental Oil Company</u>	8. Farm or Lease Name <u>STATE A-33</u>
3. Address of Operator <u>Box 460, Hobbs, New Mexico</u>	9. Well No. <u>8</u>
4. Location of Well UNIT LETTER <u>L</u> <u>2060</u> FEET FROM THE <u>SOUTH</u> LINE AND <u>660</u> FEET FROM THE <u>WEST</u> LINE, SECTION <u>33</u> TOWNSHIP <u>18-S</u> RANGE <u>37-E</u> NMPM.	10. Field and Pool, or Wildcat <u>Revers 7 Revers Ques</u>
15. Elevation (Show whether DF, RT, CR, etc.) <u>3646' DF</u>	12. County <u>LEA</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is proposed to plug & abandon this well by the following procedures:

Spot a 25 sx cmt. plug on bottom to cover perms from 3148' to 3197'. Fill well bore w/ 10 # mud & spot a 10 sx cmt plug at surface. Cap well with dry hole marker and restore location.

NMOCC - 3

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>[Signature]</u>	TITLE <u>Administrative Section Chief</u>	DATE <u>12-2-70</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>SUPERVISOR DISTRICT</u>	DATE <u>DEC 4 1970</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

FEB 5 1970

OIL CONSERVATION COM. 110000, N. M.