

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	<u>B-2456</u>

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator <u>Continental Oil Company</u>	8. Farm or Lease Name <u>State A-33</u>
3. Address of Operator <u>Box 460, Hobbs, New Mexico</u>	9. Well No. <u>11</u>
4. Location of Well UNIT LETTER <u>G</u> <u>2310</u> FEET FROM THE <u>north</u> LINE AND <u>2310</u> FEET FROM THE <u>East</u> LINE, SECTION <u>33</u> TOWNSHIP <u>18-S</u> RANGE <u>38-E</u> NMPM	10. Field and Pool, or Wildcat <u>Barrocas 7 Rivers Q. W.</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>3638' DF</u>	12. County <u>Lea</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

This well was plugged and abandoned by the following procedures.

Spotted a 40 sx cmt plug over perfor from 3151' to 3161'. Filled well bore with 10# mud & set a 10 sx cmt plug at surface. Capped well with dry hole marker. Work started and completed on 1-13-71. Left 5 1/2" 17# casing in hole from surface to 3196'.

NMCCC 3 File

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>M. E. [Signature]</u>	TITLE <u>Administrative Section Chief</u>	DATE <u>2-3-71</u>
APPROVED BY <u>John W. Runyan</u>	TITLE <u>Geologist</u>	DATE <u>MAR 22 1971</u>
CONDITION OF APPROVAL, IF ANY:		