

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs NM 88241-1980  
DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210  
DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO.	30-025-07566
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	NORTH HOBBS (GB/SA) UNIT
8. Well No.	331
9. Pool name or Wildcat	

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	2. Name of Operator ALTURA ENERGY, LTD.
3. Address of Operator P.O. BOX 4294 HOUSTON, TEXAS 77210-4294	4. Well Location Unit Letter <u>J</u> : <u>1980</u> Feet From The <u>SOUTH</u> Line and <u>2310</u> Feet From The <u>EAST</u> Line Section <u>34</u> Township <u>18-S</u> Range <u>38-E</u> NMPM <u>LEA NM</u> County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12/12/97 1. MIRU PULLING UNIT ND WELL NUBOP.  
12/13/97 2. KILL WELL PULL 129 JTS 2-3/8" TBG L/D SUMMERGIBLE.  
3. RIH W/WL 5-1/2" CIBP SET AT 4043'.  
4. RIH W/TBG 129 JTS 2-3/8".  
5. RD INSTALL FENCE BACK ON LOC.  
12/20/97 6. CIRC HOLE W/ MLF.  
7. SPOT 25 SXS CMT FROM 4000'-3753'.  
8. PERF @ 1920' PRESSURE UP TO 1000# NO BLEED OFF.  
9. NOTIFIED OCD (GARY) OK TO PUMP 25 SXS FROM 1950'.  
10. SPOT 25 SXS CMT FROM 1945'-1698'.  
11. PERF @ 304' SQZ 65 SXS 5-1/2"x7" CSG TO SURF.  
12/21/97 12. RD UNIT INSTALL DRY HOLE MARKER.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jose A. Gutierrez TITLE P&A SUPERVISOR DATE 12/13/97  
TYPE OR PRINT NAME JOSE A. GUTIERREZ TELEPHONE NO. 505-392-6498

(This space for State Use)

APPROVED BY Johnny Robinson TITLE  DATE   
CONDITIONS OF APPROVAL, IF ANY: ICJ CW NO D.H.M