

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES REQUIRED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Rev 15c 10-1-75

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

CIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name N. HOBBS (G/SA) UNIT
Name of Operator SHELL WESTERN E&P INC.	8. Farm or Lease Name SECTION 34
Address of Operator P. O. BOX 576, HOUSTON, TEXAS 77001 (WCK 4435)	9. Well No. 331
Location of Well UNIT LETTER J 1980 FEET FROM THE SOUTH LINE AND 2310 FEET FROM THE EAST LINE, SECTION 34 TOWNSHIP 18S RANGE 38E N.M.P.M.	10. Field and Pool, or Widest HOBBS (G/SA)
15. Elevation (Show whether DF, RT, GR, etc.) 3630' GR	12. County LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPER. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☒ Zone test	CASING TEST AND CEMENT JOB ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

1. POH w/prod equip.
2. CO to 4214'.
3. Set CIBP @ 4195'.
4. Install prod equip & return well to prod.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

ISSUED A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE 6-13-88

ORIGINAL SIGNATURE

APPROVED BY DISTRICT SUPERVISOR TITLE DISTRICT SUPERVISOR DATE