

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-73

|                        |  |
|------------------------|--|
| NO. OF COPIES RECEIVED |  |
| DISTRIBUTION           |  |
| SANTA FE               |  |
| FILE                   |  |
| U.S.G.S.               |  |
| LAND OFFICE            |  |
| OPERATOR               |  |

5a. Indicate Type of Lease  
State ☐ Fee ☒  
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO SEEPER OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

CIL WELL ☒ GAS WELL ☐ OTHER ☐  
Name of Operator  
SHELL WESTERN E&P INC.  
Address of Operator  
P. O. BOX 576, HOUSTON, TEXAS 77001 (WCK 4435)  
Location of Well  
UNIT LETTER 0 1320 FEET FROM THE SOUTH LINE AND 2310 FEET FROM THE EAST LINE, SECTION 34 TOWNSHIP 18-S RANGE 38-E NMPM.  
7. Unit Agreement Name  
N. HOBBS (G/SA) UNIT  
8. Farm or Lease Name  
SECTION 34  
9. Well No.  
341  
10. Field and Pool, or Widened  
HOBBS (G/SA)  
11. Elevation (Show whether DF, RT, GR, etc.)  
3620' GR  
12. County  
LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

|                                                |                                                      |                                                     |                                               |
|------------------------------------------------|------------------------------------------------------|-----------------------------------------------------|-----------------------------------------------|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/>            | REMEDIAL WORK <input type="checkbox"/>              | ALTERING CASING <input type="checkbox"/>      |
| TEMPORARILY ABANDON <input type="checkbox"/>   | CHANGE PLANS <input type="checkbox"/>                | COMMENCE DRILLING OPER. <input type="checkbox"/>    | PLUG AND ABANDONMENT <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/>  | OTHER <input checked="" type="checkbox"/> DAP & Acdz | CASING TEST AND CEMENT JOB <input type="checkbox"/> | OTHER <input type="checkbox"/>                |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. POH w/prod equip.
2. DO CIBP @ 4165'. CO to PBTD @ 4235'.
3. Perf Grayburg 4052'-86' (2 JSPP).
4. Acdz perfs 4052' - 4192' & OH 4194' - 4235' w/2400 gals 15% HCl + 1550# rock salt using RBP & PKr.
5. POH w/RBP & PKr.
6. Install prod equip & return well to prod.

I, hereby certify that the information above is true and complete to the best of my knowledge and belief.

ISSUED A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE 6-13-88

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE JUN 20 1988