

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-77

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fed ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.

OIL WELL ☒ GAS WELL ☐ OTHER ☐
Name of Operator
SHELL WESTERN E&P INC.
Address of Operator
P. O. BOX 576, HOUSTON, TEXAS 77001 (WCK 4435)
Location of Well
UNIT LETTER 0 1320 FEET FROM THE SOUTH LINE AND 2310 FEET FROM THE EAST LINE, SECTION 34 TOWNSHIP 18-S RANGE 38-E

7. Unit Agreement Name
N. HOBBS (G/SA) UNIT
8. Form or Lease Name
SECTION 34
9. Well No.
341
10. Field and Pool, or Window
HOBBS (G/SA)
11. Elevation (Show whether DF, RT, GR, etc.)
3620' GR
12. County
LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

REPAIR REMEDIAL WORK ☐ TEMPORARILY ABANDON ☐ WELL OR ALTER CASING ☐ OTHER ☐	PLUG AND ABANDON ☐ CHANGE PLANS ☐ ZONE TEST ☒	REMEDIAL WORK ☐ COMMENCE DRILLING OPER. ☐ CASING TEST AND CEMENT JOBS ☐ OTHER ☐	ALTERING CASING ☐ PLUG AND ABANDONMENT ☐
---	--	---	--

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Pull prod equip.
2. CO to $\pm 4235'$.
3. Set RBP @ $\pm 4165'$.
4. Set pkr @ 4050'. Pres tst annulus to 500#. POH w/pkr.
5. Install prod equip & return well to prod.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

E. C. Carter A 1 5000 SUPERVISOR, REG. & PERMITTING MAY 18, 1987

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISOR

MAY 22 1987

RECEIVED
MAY 21 1967
OCD
AGENCY OFFICE