State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

FILE IN TRIPLICATE	OIL CONSERVA	TION DIVISION			
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	2040 Pacheco St. Santa Fe, NM 87505		WELL API NO. 30-025-07575		
DISTRICT II	Santa Pe,	NW 67303	5. Indicate Type of Leas	SIE	
811 S. 1st Street, Artesia, NM 88210				TATE [FEE X
DISTRICT III			6. State Oil & Gas Leas	e No.	
1000 Rio Brazos Rd, Aztec, NM 87410				***************************************	
SUNDRY NOTICES AND REPORTS ON WELLS					
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"			7. Lease Name or Unit A	Agreemen	t Name
(FORM C-101 FOR SUCH PROPOSALS.)			SOUTH HOBBS (G	/SA) UN	TIT
1. Type of Well:	C WILL ON BU	ECTOD (CHUTTAN)			
Oil Well 2. Name of Operator	Gas Well Other INJ	ECTOR (SHUT IN)	8. Well No. 001		
OCCIDENTAL PERMIAN LTD.			001		
3. Address of Operator	9. Pool name or Wildca	t	HOBBS (G/SA)		
1017 W. Stanolind Rd., HOBBS,	NM 88240 505/397	-8200			
4. Well Location					
Unit Letter D : 660	Feet From The NORTH I	Line and 660 Fee	t From The WES	7	Line
Section 34	Township 18S	Range 38E	NMPM		LEA County
	10. Elevation (Show whether DF, RK) 3630' GL	B, RT GR, etc.)			
11. Chec	k Appropriate Box to Indicate Nat	ure of Notice, Report, or C	Other Data	.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
NOTICE OF INT		SUBS	SEQUENT REPOR	RT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON X	REMEDIAL WORK	ALT	ERING C	ASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OP	NS. PLU	JG & ABA	ANDONMENT
	or with the control of the control o	CASING TEST AND CEMEN			
PULL OR ALTER CASING	<u> </u>	OTHER:			F
OTHER:					
12. Describe Proposed or Completed Operation	ons (Clearly state all pertinent details, and	give pertinent dates, including			
SEE RULE 1103.	Noti	ify the NMOCD before rigg	ing up. (393-6161)		
Well is a TA'd well. CIBP set @4050	· .		123456		
Spot 35 sxs cmt on CIBP @4050'. TOC @4015'.					
Circ Mud Gel from 4015' to 3925'. Spot cmt from 3925' to 3825'. Top of 5" liner @3872'. — TAG					
SEE RULE 1103. Well is a TA'd well. CIBP set @4050'. Spot 35 sxs cmt on CIBP @4050'. TOC @4015'. Circ Mud Gel from 4015' to 3925'. Spot cmt from 3925' to 3825'. Top of 5" liner @3872'. — TAG Circ Mud Gel from 3825' to 2650'. Spot cmt from 2650' to 2550'. Bot of Anhy @2600'.					
Spot cmt from 2650' to 2550'. Bot of Anhy @2600'.					
Circ Mud Gel from 2550 to 1700. Spot cmt from 1700' to 1550'. Top of Anhy @1600'. Bot of 10-3/4" csg @1647'. — TAG					
Circ Mud Gel from 1550' to 400'. Spot cmt from 400' to 300'. — TAG					
Spot Mud Gel from 300' to 60'.	_		(C)	GLB/	•
Spot cmt from 60' to surface.			001300		
Install dry hole marker. SHU 001, U	$IL - D$, 660 FNL, 660 FWL. Sec - $\frac{1}{2}$	34, T-18S, R-38E			
I hereby certify that the information above is	true and complete to the best of my knowle	edge and belief.			
SIGNATURE Robert	Lilbert	TITLE SR. ENGR. TE	СН	DATE	08/28/2002
TYPE OR PRINT NAME Robert Gilb	ert		TELEPHO	NE NO.	505/397-8206
(This space for State Use)					SEP 0 3 200
APPROVED BY	ORIGINA	IL BICINFO BY		DATE	SEP 0 3 200
CONDITIONS OF APPROVAL IF ANY:	gary w	. WINK	ng a samue takingi yakin in Bir tili sahasa sasa		
CC HELD RAPIE EDWATS FON MUST BE NOTIFIED 24					
HOURS PRIOR TO THE BEGINNING OF					
PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.					