9. Pull tbg. to 375 10. Spot 10 sx. cmt. 11. Install dry hole	marker & clean loca	ition, move off unit.	Ompleted 8-24-73  DATE 9-25-74
9. Pull tbg. to 375 10. Spot 10 sx. cmt. 11. Install dry hole	marker & clean loca	Work Content to the best of my knowledge and belief.	Ompleted 8-24-73
9. Pull tbg. to 375 10. Spot 10 sx. cmt. 11. Install dry hole	marker & clean loca	ition, move off unit. . Work c	ompleted 8-24-73
9. Pull tbg. to 375	marker & clean loca	ition, move off unit.	ompleted 8-24-73
9. Pull tbg. to 375 0. Spot 10 sx. cmt.	marker & clean loca	ition. move off unit.	
9. Pull tbg. to 375	marker & clean loca	ition. move off unit.	
9. Pull tbg. to 375	marker & clean loca	tion. move off unit.	
9. Pull tbg. to 375 0. Spot 10 sx. cmt.	marker & clean loca	ition. move off unit.	
9. Pull tbg. to 375			
8. Run 2 3/8" tbg to	plug in top of surf	mt.plug. POH w/ tbg.	
7. Cut 5½" @ 1075'	o 1100' spotted 38 s	x. cmt. plug.	
6. Cut 511 @ 15381 8	s could not pull.		
4. Cut 511 @ 2047 b	out still could not	pull. 8 sx. cmt. plug. POH w/ tbg.	
3. Cut $5\frac{1}{2}$ csg. @ 40	)25' w/ jet cutter b	cement w/ dump bailer. ( 3 ut could not pull.	30.7
1. MIRU Service rig.	POH w/ 2 3/811 tbg		sx.)
17. Describe Proposed or Complework) SEE RULE 1103.	eted Operations (Clearly state all	permen access, and good possession	
OTHER		I portinent details and give pertinent dates, in	cluding estimated date of starting any proposed
PULL OR ALTER CASING		OTHER	L
TEMPORARILY ABANDON	CHANGE PL	COMMENCE DRILLING OPNS.  CASING TEST AND CEMENT JQB	
PERFORM REMEDIAL WORK	PLUG AND		ALTERING CASING PLUG AND ABANDONMENT
	OF INTENTION TO:	SUBSEQ	UENT REPORT OF:
116. Cho	eck Appropriate Box To	Indicate Nature of Notice, Report of	or Other Data
	15, Elevation (S 3642 DF	how whether DF, RT, GR, etc.)	Lea
THE East LINE,		1P 18S RANGE 39E	NMPM.
<b>3</b> 1111 ==			<i>(((((((((((((((((((((((((((((((((((((</i>
. Location of Well		South LINE AND 330 FEET	
. Address of Operator P.O. Box 657 Hobbs.	New Mexico 83240		10. Field and Pool, or Wildcat
DA&S 011 Well Servic	ing, incorporated		9. Well No.
OIL WELL OTHER.			8. Farm or Lease Name
	ICATION FOR PERMIT = (1 SILL		7. Unit Agreement Name
SUN	DRY NOTICES AND REP	ORTS ON WELLS EN OR PLUG BACK TO A DIFFERENT RESERVOIR. 101) FOR SUCH PROPOSALS.)	
PERATOR			THIRD THE THE
AND OFFICE			5. State Oil & Gas Lease No.
.s.g.s.			State Fee X
	NEW MEXICO	OF CONSERVATION COMMISSION	5a. Indicate Type of Lease
FE	NEW MEXICO	OIL CONSERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
			Supersedes Old