OIL CONSERVATION COMMISSION

HOBBS. NEW MEXICO

iday 8, 1957

Bishop Canyon Uranium Corp. Box 2016 Hobbs, New Mex.

Gentlemen:

Mr. W. A. Gressett, Oil & Gas Inspector for the Commission, has made an inspection of the location for your Hardin No. 1 in Unit B of Section 6, T-18-S, R-39-E and has found that the legal description of the location has not been inscribed on the marker as required.

Please notify this office when this has been done so that a final inspection may be made.

Yours very truly,

OIL CONSERVATION COMMISSION

R. F. Montgomery Proration Manager

mc