DISTRIBUTION SANTA FE		Form C-103
SANTA FE		Supersedes Old C-102 and C-103
	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
FILE	1	
u.s.g.s.	JAN 27 3 43 PM 166	5a. Indicate Type of Lease
LAND OFFICE	2 42 LM 00	State Fee.
OPERATOR		5. State Oil & Gas Lease No.
		<del>-                                    </del>
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)  1.		7, Unit Agreement Name
OIL GAS WELL WELL	OTHER-	7, Olik rigitedilelik i valle
2. Name of Operator  Culf Oil Corporation  3. Address of Operator  Box 670, Robbs, New Mexico  4. Location of Well  Unit Letter N 660 FEET FROM THE South Line and 2103 FEET F		8. Farm or Lease Name
		C. O. Davis
		9. Well No.
		1
		10. Field and Pool, or Wildcat
		Fest Hobbs SA
	···	
THE West LINE, SECTION	ON 29 TOWNSHIP 18-S RANGE 39-E NM	PM. (()()()()()()()()()()()()()()()()()()(
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	3593 GL	Lea
6. Check	Appropriate Box To Indicate Nature of Notice, Report or	Other Data
		ENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
<u> </u>	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
TEMPORARILY ABANDON	CHANGE PLANS CASING TEST AND CEMENT JOB	-
PULL OR ALTER CASING	OTHER	
	OTALK	
OTHER	Actidized	
17. Describe Proposed or Completed Or	perations (Clearly state all pertinent details, and give pertinent dates, include	ling estimated date of starting any proposed
	····	
	up. Dumped 1000 gallons of 15% NE double inhib La of cil. Swabbed and cleaned up. Ran rods a	
Pulled rods and pum Flushed with 25 barrels well to production.  18. I hereby certify that the information that the information of the production of the pro	n above is true and complete to the best of my knowledge and belief.	and pump and returned
Pulled rods and pum Flushed with 25 barrels well to production.  18. I hereby certify that the information of the control of t	s of cil. Swabbed and cleaned up. Ran rods a	
Pulled rods and pum Flushed with 25 barrels well to production.  18. I hereby certify that the information of the certific that the certific that the information of the certific that the certi	n above is true and complete to the best of my knowledge and belief.	and pump and returned