NO. OF COPIES RECEIVED		Form C-103
DISTRIBUTION		Supersedes Old C-102 and C-103
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
FILE		5a. Indicate Type of Lease
U.S.G.S.	the state of the s	State Fee
LAND OFFICE	-	5. State Oil & Gas Lease No.
OPERATOR	_	0, 61410 011 0 2 1 1 1 1 1 1
SUNDS	RY NOTICES AND REPORTS ON WELLS OPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOI FION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	$_{\rm IR}$. $\left\{\left\{\left\{\left\{\left\{\left\{\left\{\left\{\left\{\left\{\left\{\left\{\left\{\left\{\left\{\left\{\left\{\left\{\left\{$
	FION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	7. Unit Agreement Name
l. OIL GAS		
2. Name of Operator	OTHER-	8. Farm or Lease Name
		C. O. Davis
(h) f O4] Corporation 3. Address of Operator		9. Well No.
	. 0001.0	2
Box 670 Hobbs, New Me	x160 88240	10. Field and Pool, or Wildcat
1 -	1980 FEET FROM THE SOUTH LINE AND 660	Hobbs. East Sen Andres
UNIT LETTER,	FEET FROM THE SONGE LINE AND	The same of the sa
l	ION 29 TOWNSHIP 18-S RANGE 39-E	
THE LINE, SECT	ION TOWNSHIP ID-D RANGE	
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	3597' OI.	Lea
16. Check	Appropriate Box To Indicate Nature of Notice, Repo	ort or Other Data
	· • · · ·	SEQUENT REPORT OF:
Notice of	HT ZWYJOW YOU	
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JO	QB
	OTHER	
OTHER		
	Cleaned out and	d acidizad
17. Describe Proposed or Completed (work) SEE RULE 1603.	Operations (Clearly state all pertinent details, and give pertinent date	s, including estimated date of starting any proposed
in little with 2000 re	with sand pump from hh65' to hh70'. Treadlons of 15% NE acid. Flushed with 2h bar R 1.5 bpm. Ran tubing rods and pump and s	Lists of ilesu agre. wer-
	on above is true and complete to the best of my knowledge and belief.	
ORIGINAL SIGNED C. D. BORLAND APPROVED BY CONDITIONS OF APPROVAL, IF AR	TITLE Area Production Man	