Submit 3 Copies To Appropriate District Office	State of New Michieu				Form C-103 Revised March 25, 1999	
Energy, Minerals and Natural Resources 625 N. French Dr., Hobbs, NM 88240			WELL API NO.			
District II	istrict II ONICED VATION DIVISION			30-025-07945		
811 South First, Artesia, NM 88210 OIL CONSERVATION DIVISION District III 2040 South Pacheco				5. Indicate Type of Lease		
1000 Rio Brazos Rd., Aztec, NM 87410 Conto Ec. NIM 97505				STATE FEE 🔼		
District IV 2040 South Pacheco, Santa Fe, NM 87505				6. State Oil &	Gas Lease No.	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other				7. Lease Name or Unit Agreement Name: Carrie O. Davis		
Oil Well				8. Well No.		
EnerQuest Resources. LLC				3		
3. Address of Operator				9. Pool name or Wildcat		
P. O. Box 11150, Midland, TX 79702 4. Well Location				Hobbs, E.	(San Andres)	
Unit Letter M: 990 feet from the south line and 990 feet from the west line						
Section 29	Township 189	S Rai	nge 39E	NMPM Lea	County	
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3597' GR						
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data						
				SEQUENT R		
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK					ALTERING CASING \square	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT						
PULL OR ALTER CASING			CASING TEST AN	ND 🗆	ADAINDONNEIT	
OTHER:			OTHER:			
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.						
4—18—02: MIRU Triple N Rig #25 & plugging equipment. NO wellhead & NUBOP. RU gauge ring on wireline. RIH w/wireline. Stacked out @ 2860'. POOH w/wireline. RIH w/notched collar, perf sub & 107 jts 2 3/8" work string. Load hole & pumped 35 sk "C" plug @ 3317'. POOH w/tbg. SI well & SD for weekend.						
4—19—02: RIH w/tbg & tagged cmt @ 2976'. Circ hole w/mud. POOH w/tbg. RIH w/wireline & perf csg @ 800'. POH w/wireline. RIH w/packer to 527'. Loaded hole & set packer, est rate @ 200 psi & squeezed 75 sks "C" cmt 800' - 700'. ISIP 150 psi. WOC 1 hr & POH w/packer. WOC & RIH w/wireline. Tagged cmt @ 400'. POOH w/wireline. NDBOP & pumped 10 sks "C" cmt from 60' to surf. POOH w/tbg. Release Triple N. ALL PLUGGING APPROVED BY JOHNNY ROBINSON & E. L. GONZALES W/NMOOD.						
I hereby certify that the information above is true and complete to the best of my knowledge and belief.						
α //	_ <				- · o - m m	
SIGNATURE (TITLE_	Vice President		DATE_ <u>05-02-02</u> _ 85311	
Type or print name Christopher P. Renaud Telephone No. 915						
(This space for State use)	01. 81				AUG 1 4 2002	
APPPROVED BY	ry (Kolinson	ritle_	TOMPI IANCE (DATE	
Conditions of approval, if any:	0					

S CMM