

Cities Service Oil and Gas Corp. SMGSAU Tract 1 Well No. 3, Lea County, New Mexico
attachment

6. Squeeze the Base of the Salt thru squeeze Perfs @ + 2700' w/300 sacks of Class C w/2% CaCl₂ cement. PCO retainer set @ + 2600' and dump 20 sacks of cement on top of retainer. POOH w/tubing.
7. RIH w/tubing and retainer and set retainer @ 1300'. Squeeze casing leak @ 1393 - 1422' w/300 sacks of Class C w/2% CaCl₂ cement.
8. PCO retainer and fill casing from 1300' to the surface w/150 sacks of Class C w/2% CaCl₂ cement. *Both sides of csg.*
9. Cut off WI and install a 4" dry hole marker to designate a plugged and abandoned location.

① Perf above retainer (6 1/2" csg)

RECEIVED
MAR 17 1986
O.C.D.
HOBBS OFFICE