

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name N. HOBBS (G/SA) UNIT
2. Name of Operator SHELL OIL COMPANY	8. Farm or Lease Name SECTION 28
3. Address of Operator P. O. BOX 991, HOUSTON, TEXAS 77001	9. Well No. 241
4. Location of Well UNIT LETTER N 330 FEET FROM THE SOUTH LINE AND 2310 FEET FROM THE WEST LINE, SECTION 28 TOWNSHIP 18-S RANGE 38-E NMPM.	10. Field and Pool, or Wildcat HOBBS (G/SA)
11. Elevation (Show whether DF, RT, GR, etc.) 3646' GR	12. County LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

FORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PARABLY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
OR ALTER CASING <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Clean out to PBTD + 4225'.
- Acidize SA perfs w/5,000 gals 15% HCl-NEA (4110' - 4220').
- Perforate 4124' - 32', 4104' - 18', 4088' - 92', 4061' - 74' (43', 86 holes).
- Acidize new perfs w/4,000 gals 15% HCl NEA.
- Run production equipment and return to production.

by certify that the information above is true and complete to the best of my knowledge and belief.

A. J. Fore
A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE OCTOBER 14, 1982
ORIGINAL SIGNED BY
JERRY SEXTON
BY DISTRICT SUPERVISOR TITLE DATE OCT 19 1982
INS OF APPROVAL, IF ANY:

1

RECEIVED
OCT 18 1982
G. C. D.
HUBBARD OFFICE