

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRI-
(Other instruction
verse side)

ATE
17 70

Budget Bureau No. 1000-
Expires August 31, 1985

2. LEASE DESIGNATION AND SERIAL NO.

LC 032233 (a)

3. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

SHELL WESTERN E&P INC.

3. ADDRESS OF OPERATOR

P. O. BOX 576, HOUSTON, TEXAS 77001 (WCK 4435)

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)

At surface

UNIT LTR O, 440' FSL & 2310' FEL

5. UNIT AGREEMENT NAME

N. HOBBS (G/SA) UNIT

6. FARM OR LEASE NAME

SECTION 30

7. WELL NO.

342

8. FIELD AND POOL, OR WILDCAT

HOBBS (G/SA)

9. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

SEC. 30, T18S-R38E

14. PERMIT NO.

NA

15. ELEVATIONS (Show whether OF, RT, GR, etc.)

3654' DF

12. COUNTY OR PARISH

LEA

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

4-02 to 4-03-87: Pulled prod equip. Tagged btm @ 4256'. Ran caliper thru OH. Dmpd 27
sx 12/20 sand dwn csg. Tagged @ 4113'. CO to 4117'. Capped w/8' hydromite to
4108'.

4-06-87: Set CICR @ 3857'. Sqzd Grayburg/San Andres OH (3974' - 4108') w/10% CaCl₂ +
1000 gals Flocheck + 100 sx Cls "C" Thixotropic cmt + 8#/sx Calseal + 2% CaCl₂.
Capped CICR w/4' cmt.

4-07 to 4-10-87: DO cmt (& CICR @ 3857') 3853' - 4110'. Pres tstd sqz to 500#, bled to
0 in 2 min. DO cmt & sand to 4180'. CO sand to 4258'.

4-11-87: Installed prod equip & returned well to prod.

ACCEPTED FOR REGISTRATION

MAY 12 1987

CARLSBAD, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

A. J. Fore

A. J. FORE

TITLE SUPERVISOR REG. & PERMITS

DATE MAY 12, 1987

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side