

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-77

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-121) FOR SUCH PROPOSALS.)

1. CIL ☒ EAB ☐ OTHER ☐
2. Name of Operator: SHELL WESTERN E&P INC.
3. Address of Operator: P. O. BOX 576, HOUSTON, TEXAS 77001 (WCK 4435)
4. Location of Well: UNIT LETTER H, 2310 FEET FROM THE NORTH LINE AND 330 FEET FROM THE EAST LINE, SECTION 32, TOWNSHIP 18-S, RANGE 38-E, N.M.P.M.
5. Unit Agreement Name: N. HOBBS (G/SA) UNIT
6. Field or Lease Name: SECTION 32
7. Well No.: 421
8. Field and Pool, or Whichever: HOBBS (G/SA)
9. Elevation (Show whether DF, RT, GR, etc.): 3636' GR
10. County: LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐ ZONE TEST ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING DEFS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

11. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Pull prod equip.
2. CO to PBTD.
3. Set CIBP @ 4155'.
4. Zone test San Andres perms 4092' - 4149' for one month.
5. Install prod equip & return well to prod.

I, I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Signed J. Curtis for A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE AUGUST 26, 1987

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

AUG 31 1987

RECEIVED

AUG 28 1987

OCD
HOBBS OFFICE