

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-20086
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil & Gas Lease No.	B-1258-1
7. Lease Name or Unit Agreement Name	New Mexico "AE" State
8. Well No.	5
9. Pool name or Wildcat	Vacuum Abo Reef
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3991' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	2. Name of Operator Texaco Exploration and Production Inc.
3. Address of Operator P.O. Box 730 Hobbs, NM 88240	4. Well Location Unit Letter K : 1980 Feet From The South Line and 1980 Feet From The West Line Section 12 Township 18S Range 34E NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3991' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☒
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Starting date 1/22/93

1. RIH w/ 2-7/8" CIBP & set @ 8070'. Cap w/ 1 sx cmt.
 2. Load hole w/ mud laden fluid.
 3. RIH w/ 2-7/8" CIBP & set @ 6100'. Cap w/ 1 sx cmt.
 4. RIH w/ 2-7/8" CIBP & set @ 5070'. Cap w/ 1 sx cmt.
 5. Cut & pull 3305' of 2-7/8" csg. Spot 45 sx stub plug. Tagged TOC @ 3184'.
 6. Spot 30 sx class "C" cmt @ 2905'.
 7. Spot 30 sx class "C" cmt @ 1800'.
 8. Spot 35 sx class "C" cmt @ 400'. Tagged TOC @ 256'.
 9. Spot 10 sx surf. plug.
 10. Cut off WH & anchors. Install DH marker.
- Completion date 3-31-93

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Monte C. Duncan TITLE Engineer's Assistant DATE 4-2-93
TYPE OR PRINT NAME Monte C. Duncan TELEPHONE NO. 393-7191

(This space for State Use)

APPROVED BY Larry W. Hill TITLE OIL & GAS INSPECTOR DATE APP 2 8 1993
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

APR 01 1952

OLD HOUSE BOOKS