/10	m 3160-5 vember 1983) rmerly 9-331)	DEPART	UNIT STATI IENT OF THE	INTERI	BUBMIT IN TRIPLIC	• • 5. 1	Form approved. Budget Bureau N Expires August 3 BASE DESIGNATION A NM-025566	1, 1985		
	SUND	RY NOT	CES AND REP als to drill or to deep TION FOR PERMIT-	ORTS C	N WELLS 1 1 1924	0 6. 1	IF INDIAN, ALLOTTEE	OR TRIBE NAME		
	JUL						7. UNIT AGREEMENT NAME			
	OIL GAS X OTRES			City			Lusk Deep Unit-A			
2	NAME OF OPERATOR				AREIN	8.	FARM OR LEASE NAME	1		
	Phillips Petro	<u>leum Co</u> n	pany				Lusk Deep	Unit-A		
3.	ADDRESS OF OPERATOR					9 .	9. WBLL NO.			
	4001 Penbrook		5							
4.	4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)						10. FIBLE AND POOL, OR WILDCAT LUSK Atoka Gas &			
	At surface						Lusk-Morrow Gas 11. SPC., T., B., M., OR BLK. AND			
	Unit J, 1980'	SURVEY OR ARBA								
				<u> </u>			19, 19-S,			
14.	PERMIT NO.		16. ELEVATIONS (Sho	-	, RT, GR, etc.)	12.	COUNTY OR PARISE Lea	18. STATE NM		
	30-025-20122		3550' GI	<u> </u>	· · · · · · · · · · · · · · · · · · ·		Lea	INITI		
16.		Check A	opropriate Box To	Indicate N	ature of Notice, Report, or	Othe	r Data			
	NOTICE OF INTENTION TO : SUBBR						UBNT REPORT OF :			
	TEST WATER SHUT-OFF	. []	PULL OR ALTER CASING		WATER SHUT-OFF]	REPAIRING W			
	FRACTURE TREAT		MULTIPLE COMPLETE		PRACTURE TREATMENT	X	ALTERING CA			
	SHOOT OR ACIDIZE		ABANDON*		SHOOTING OR ACIDIZING	x	ABANDONMEN	T•		
	REPAIR WELL		CHANGE PLANS		(Other)					
	(Otber)						nultiple completion on Beport and Log form			
17.	DESCRIBE PROPOSED OR proposed work. If nent to this work.) *	COMPLETED OF well is direction	RATIONS (Clearly state onally drilled, give sul	all pertinen saurface local	t details, and give pertipent dat ions and measured and true vert	es, incl ical de	uding estimated date pths for all markers	of starting any and sones perti-		
	5-12 thru									
	5-17-89: 12,	, 412' PT	D. Rigged up	WSU.	Swbd fluid level dow	n to	11,000' from	m 3,000'.		
	wit Ene	th less t erjet gun	han 1 BO. Pe	erf'd the 13.5 gra	'-12,270' and 12,400 ru tbg using 2-1/8" am charges at 4 SPF	magn	etically dec	entralized		
	5-22-89: Rar	n 4 point	test.							

5-31-89: RU WSU. After well was perforated in new zone and higher pressures encountered, the valve above the master valve on the xmas tree started leaking around stem. Installed re-built 5000# wellhead assembly overexisting 3000# working-6000# test master valve on original tree. Installed and tested lubricator on wellhead.

Presently waiting on gas connection.

BIGNED Am Danders L. M. San	dersR	egulation &	Proration Supervisor	DATN .	June 30,	1989
(This space for Federal or State office use)						
APPROVED BY CONDITIONS OF APPROVAL, IF ANT:				DATE	· · · · · · · · · · · · · · · · · · ·	. <u></u>
				λ.		
	*See Instructio	ons on Reverse Si	de	555	5	
			$C_{i} \in \mathbb{R}^{n} \times \mathbb{R}$	•		

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the