

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

3-NMOCC  
1-File

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator <b>GETTY OIL COMPANY</b>		8. Farm or Lease Name <b>STATE AN</b>
3. Address of Operator <b>P.O. BOX 249, Hobbs, New Mexico 88240</b>		9. Well No. <b>8</b>
4. Location of Well UNIT LETTER <b>P</b> <b>330</b> FEET FROM THE <b>South</b> LINE AND <b>330</b> FEET FROM THE <b>EAST</b> LINE, SECTION <b>7</b> TOWNSHIP <b>18S</b> RANGE <b>35E</b> NMPM.		10. Field and Pool, or Wildcat <b>VACUUM DEVONIAN</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3968' D.F.</b>		12. County <b>LEA</b>

### 16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING CPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

### 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Set a CIBP in 4-1/2" Csg. at 11,400' with 20' cement on top.
- Spotted a 25 sx. cement plug at top of 4-1/2" csg. and 2-7/8" tubing stub @ 5190'.
- Spotted a 50 sx. cement plug in and out of 9-5/8" casing from 3500' to 3340'.
- Spotted a 10 sx. cement plug at surface with marker.
- Hole was loaded with mud laden fluids.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Original Signed By  
SIGNED C. L. WADE TITLE AREA SUPERINTENDENT DATE MAY 26, 1970

APPROVED BY John W. Runyan TITLE Geologist DATE

CONDITIONS OF APPROVAL, IF ANY:

WLG/bh