

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO CEMENT OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)		5a. Indicate Type of Lease State ☒ Fee ☐ 5. State Oil & Gas Lease No. B-1031
1. OIL WELL ☒ GAS WELL ☐ OTHER ☐ 2. Name of Operator TEXACO Inc. 3. Address of Operator P. O. Box 728, Hobbs, New Mexico 88240 4. Location of Well UNIT LETTER J FEET FROM THE 1650-1800 South LINE AND 1650 FEET FROM THE East LINE, SECTION 6 TOWNSHIP 18-S RANGE 35-E N.M.P.M. 15. Elevation (Show whether DF, RT, CR, etc.) 3972' (GR)		7. Unit Agreement Name 8. Farm or Lease Name TV 'AB' State 9. Well No. 5 10. Field and Pool, or Wildcat Vacuum Abo Reef 12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ TEMPORARILY ABANDON ☐ PULL OR ALTER CASING ☐ OTHER ☐	PLUG AND ABANDON ☐ CHANGE PLANS ☐ OTHER ☐
REMEDIAL WORK ☐ COMMENCE DRILLING OPNS. ☐ CASING TEST AND CEMENT JOBS ☐ OTHER ☒ Open vent string for Abo	ALTERING CASING ☐ PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rigged up.
2. Clean out & DOC 4060' - 4749'. DOC Cement retainer 5825' - 6600'. (Abandoned Elinebry) Clean out to 8817' (TD).
3. Install pumping equipment. Test & place well on production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Asst. Dist. Supt. DATE 8-4-77

City Signed by Larry Sexton TITLE Dist. 1 Supt. DATE AUG 10 1977

APPROVED BY _____

CONDITIONS OF APPROVAL, IF ANY: