Submit 3 Copies to Appropriate District Office

1. Type of Well: OIL X

4. Well Location

2. Name of Operator

3. Address of Operator

work) SEE RULE 1103.

## State of New Mexico Ene Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

County

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II P.O. Drawer DD, Artesia, NM 88210

Unit Letter A: 994 Feet From The NORTH Line and

Township 18S

## OIL CONSERVATION DIVISION

3982DF

OIL CONSERVATION DIVISION  ISTRICT II O. Drawer DD, Artesia, NM 88210  ISTRICT III OO Rio Brazos Rd., Aztec, NM 87410  OIL CONSERVATION DIVISION P 0. Box 2088 Santa Fe, New Mexico 87504-2088	WELL API NO.  3002520176  5. Indicate Type of Lease  STATE X  FEE  6. State Oil & Gas Lease No.  B-936	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE 'APPLICATION FOR PERMIT' (FORMC-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name  NEW MEXICO BO STATE	
ype of Well:  IL X GAS OTHER  FELL WELL		
ame of Operator  EXXON CORPORATION	8. Weil No. <b>7</b>	
ddress of Operator ATTN: REGULATORY AFFAIRS P. O. BOX 1600 MIDLAND, TX 79702  Yell Location	9. Pool name or Wildcat  VACUUM ABO REEF	
en Location		

**EAST** 

LEA

Range 34E

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

330

\_ Feet From The \_

Check Appropriate Box to Indicate N	ature of Notice, Report, or Other Data		
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON	REMEDIAL WORK ALTERING CASING		
TEMPORARILY ABANDON CHANGE PLANS	COMMENCE DRILLING OPNS. PLUG & ABANDONMENT		
PULL OR ALTER CASING	CASING TEST AND CEMENT JOB		
OTHER:	OTHER: ACIDIZE		
12 Describe Proposed or Completed Operations (Clearly state all partitions details and give partitions date incl. iii.			

07/22/92 ACIDIZE ABO PERS W/ 25% HCL ACID AND DIKLOR-S

dge and belief.  TITLE Sr.Staff Office Assistant	DATE 12/14/92
(915) 688-6166	TELEPHONE NO.
	DEC 21'92
	(915) 688-6166