

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 South First, Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised March 25, 1999

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

<b>WELL API NO.</b> 30-025-20282
<b>5. Indicate Type of Lease</b> STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
<b>6. State Oil &amp; Gas Lease No.</b> B-1301
<b>7. Lease Name or Unit Agreement Name:</b> Central Vacuum Unit
<b>8. Well No.</b> #109
<b>9. Pool name or Wildcat</b> Grayburg, San Andres
<b>10. Elevation (Show whether DR, RKB, RT, GR, etc.)</b>

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

**1. Type of Well:**  
Oil Well ☒ Gas Well ☐ Other ☐

**2. Name of Operator**  
Texaco Exploration & Production, Inc.

**3. Address of Operator**  
P. O. Box 3109, Midland, TX 79702

**4. Well Location**  
Unit Letter I : 2310 feet from the South line and 660 feet from the East line  
Section 6 Township 18S Range 35E NMPM Lea County

<b>11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data</b>	
<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <input type="checkbox"/>

**12. Describe proposed or completed operations.** (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

- Set 3 1/2" CIBP (6-16-99) Tag @ 4300' w/17' Cmt (Grayburg-San Andres) Spot 25 Sx plug 4300'-4100' Tag @ 3932'
- Displace hole w/MLF 9.5# Brine w/25# gel P/BBL
- Spot 30 Sx plug 3800'-3400' (Queen)
- Spot 25 Sx plug 2800'-2600' (Yates)(B-Salt)
- Perf well @ 1600' (7 5/8" shoe, T-Salt) unable to Sqz spot 30 Sx plug 1643'-1200' Tag @ 1015
- Circ Cmt 30' to Surf w/10 Sx, Install dry hole marker. 8/30/01

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jimmy Bagley TITLE MANAGER DATE 8-30-01

Type or print name Jimmy BAGLEY Telephone No. 915 683 4996  
(This space for State use)

APPROVED BY Johnny Robinson TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
Conditions of approval, if any:

GWW