

Surface location in Unit E Sec. 12-185-34E
Bottomed in Unit H Sec. 11-185-34E 44.18E + 2047.49 ~~W~~N
Perforations to be held to at least 8723' measured
depth from the surface.

Nutters letter of July 9, 1963