

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-20310
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. B-1258-1
7. Lease Name or Unit Agreement Name New Mexico "AE" State
8. Well No. 13
9. Pool name or Wildcat Vacuum Abo Reef

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
Texaco Exploration and Production Inc.

3. Address of Operator
P.O. Box 730 Hobbs, NM 88240

4. Well Location
Unit Letter A : 990 Feet From The North Line and 660 Feet From The East Line
Section 11 Township 18S Range 34E

10. Elevation (Show whether DF, RKB, RT, GR etc.)
4007' DF

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☒
PULL OR ALTER CASING ☐		CASING TEST AND CEMENT JOB ☐	
OTHER: ☐		OTHER: ☐	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. RIH w/ 2-7/8" CIBP & set @ 8094'. Cap w/ 1 sx cmt. Starting date 1/21/93
2. Load hole w/ mud laden fluid.
3. RIH w/ 2-7/8" CIBP & set @ 5900'. Cap w/ 1 sx cmt.
4. RIH w/ 2-7/8" CIBP & set @ 4870'. Cap w/ 1 sx cmt.
5. Cut & pull 3100' of 2-7/8" csg. Spot 66 sx stub plug. Tagged TOC @ 2870'.
6. Spot 35 sx class "C" cmt @ 1792'.
7. Spot 35 sx class "C" cmt @ 409'. Tagged TOC @ 290'.
8. Spot 10 sx surf. plug.
9. Cut off WH & anchors. Install DH marker.

Completion date 3-31-93

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Monte C. Duncan TITLE Engineer's Assistant DATE 4-2-93

TYPE OR PRINT NAME Monte C. Duncan TELEPHONE NO. 393-7191

(This space for State Use)

APPROVED BY [Signature] TITLE OIL & GAS INSPECTOR DATE JUN - 8 1993

CONDITIONS OF APPROVAL, IF ANY: