

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
B-1258-1

SUNDY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO CEMENT OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name
2. Name of Operator	8. Farm or Lease Name
TEXACO Inc.	New Mexico 'AE' State
3. Address of Operator	9. Well No.
P.O. Box 728 Hobbs, New Mexico 88240	13
4. Location of Well	10. Field and Pool, or Wildcat
UNIT LETTER <u>A</u> <u>990</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM	Vacuum Abo Reef
THE <u>East</u> LINE, SECTION <u>11</u> TOWNSHIP <u>18-S</u> RANGE <u>34-E</u> N.M.P.M.	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
4007' (DF)	Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☒	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rigged up. Install BOP. Pull tubing.
2. Acidize 2-7/8" Csg perforations 8148'-8902' w/4500 gal 15% NE Acid in 3 equal stages using 800# rock salt between stages.
3. Install production equipment. Test and return to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Asst. Dist. Supt. DATE 6-28-77

APPROVED BY [Signature] TITLE [Signature] DATE 6/28/77

CONDITIONS OF APPROVAL, IF ANY: