

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 063586

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Lusk Deep

8. FARM OR LEASE NAME

Southern Calif. Fed

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

11. ACQ. T. R. M. OR BLM. AND  
SURVEY OR AREA

29 - 19S - 32E

12. COUNTY OR PARISH

Lea

13. STATE

N.M.

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☐ GAS WELL ☒ OTHER ☐

2. NAME OF OPERATOR

El Paso Products Company

3. ADDRESS OF OPERATOR

c/o Hobbs Pipe &amp; Supply Box 2010 Hobbs, New Mex.

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

1980' FSL &amp; 1980' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

UK

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON\* ☐CHANGE PLANS ☐

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT\* ☒(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any  
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-  
nent to this work.)

- 1 - Spotted a 25 sk cement plug to cover existing perfs.
- 2 - Spotted a 25 sk cement plug at stub of 4 1/2" csg. 4700'
- 3 - Spotted a 35 sk cement plug at base of 8 5/8" csg. (4604')
- 4 - Spotted a 25 sk cement plug at 2400' - 2500'
- 5 - Spotted a 25 sk cement plug at 800' - 900'
- 6 - Spotted a 10 sk cement plug at top
- 7 - Hole was loaded w/mud laden fluids & a 4" reg. marker erected.
- 8 - Well was plugged and abandoned on 11/10/71

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature]TITLE AgentDATE 11/19/71

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

TITLE \_\_\_\_\_

APPROVED

FEB 4 1972

\*See Instructions on Reverse Side

JUL 4 1972  
ACTING DISTRICT ENGINEER

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 42-R14

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☐ OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR  
El Paso Products Company

3. ADDRESS OF OPERATOR

c/o Hobbs Pipe & Supply Co., Box 2010, Hobbs, N. M.

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

1980' FSL & 1980' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

UK

5. LEASE DESIGNATION AND SERIAL NO.

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Lusk Deep

8. FARM OR LEASE NAME

Southern Calif. Fed

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

29 - 19S - 32E

12. COUNTY OR PARISH

Lea

13. STATE  
N. M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

XX

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*  
(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

Proposed Plugging Procedures:

1. Spot a 25 sx cement plug to cover existing perforations.
2. Spot a 25 sx cement plug at stub of 4-1/2" casing.
3. Spot a 25 sx cement plug at 7,000', if this much casing is recovered.
4. Spot a 35 sx cement plug at base of 8-5/8" casing (4604').
5. Spot a 25 sx cement plug at 2400' - 2500'.
6. Spot a 25 sx cement plug at 800' - 900'.
7. Spot a 10 sx cement plug at top.
8. Hole will be loaded with mud-laden fluids and a 4" regular marker erected.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Agent

DATE

9/16/71

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED

DATE

\*See Instructions on Reverse Side

SEP 17 1971  
J. I. GORDON  
PLUG DISTRICT ENGINEER

RECEIVED

SEP 21 1971

OIL CONSERVATION COMM.  
HOBBS, N. M.