

COPIES RECEIVED		
DISTRIBUTION		
SATISFA		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
B-1258-1	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name	
2. Name of Operator		8. Farm or Lease Name	
TEXACO INC.		N.M. 'AE' State	
3. Address of Operator		9. Well No.	
P.O. Box 728 - Hobbs, New Mexico 88240		14	
4. Location of Well		10. Field and Pool, or Wildcat	
UNIT LETTER B, 990 FEET FROM THE North LINE AND 1980 FEET FROM		Vacuum Abo Reef	
THE East LINE, SECTION 11 TOWNSHIP 18-S RANGE 34-E N.M.P.M.			
15. Elevation (Show whether DF, RT, GR, etc.)		12. County	
4013' (DF)		Lea	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rig up.
2. Set CIBP @ 5048'.
3. Plug & abandon subject well with following cement plugs:  
2 7/8" OD csg plug 5040-4840 w/5 sacks cement  
2 7/8" OD csg plug 1750-1550 w/5 sacks cement  
Inside 8 5/8" & 2 7/8". Csg plug 300' - surface w/125 sacks cement.
4. Well plugged & abandoned 10-29-75.
5. Install Dry Hole Marker. Clean location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED John W. Runyan TITLE Assistant District Supt. DATE 11-5-75  
APPROVED BY Geologist TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY: