

OIL CONSERVATION DIVISION 1 File

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-77

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State Fee
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL GAS WELL OTHER
2. Name of Operator: Penroc Oil Corporation
3. Address of Operator: P.O. Box 5970 Hobbs, New Mexico 88241
4. Location of Well: UNIT LETTER M, 660 FEET FROM THE West LINE AND 510 FEET FROM THE South LINE, SECTION 8 TOWNSHIP 18 RANGE 35 NMPM.
10. Field and Pool, or Wildcat: Vacuum Devonian, Mid
15. Elevation (Show whether LF, RT, CB, etc.): 3951.4
12. County: Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING OTHER CASING TEST AND CEMENT JOB
OTHER

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

RU & drill out CIBP @ 8772' & 8825' & Clean out to 11570' Set cement retainer @ ≈ 11450' & squeeze Devonian perfs with 150 sx cement. Pick up second cement retainer and squeeze ABO perfs with 150 sx cement. WOC. Drill out and test squeeze jobs. Spot acid & perforate Devonian treat if necessary with 500 gal. acid. Test.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Mohammed Yamin Merchant TITLE President DATE 8/4/87

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT I SUPERVISOR TITLE DATE AUG 5 1987

CONDITIONS OF APPROVAL, IF ANY:

7A