

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

3-NMOCC
1-File

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

3a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
4. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator GETTY OIL COMPANY		8. Farm or Lease Name STATE AN
3. Address of Operator P.O. BOX 249, HOBBS, NEW MEXICO 88240		9. Well No. 9
4. Location of Well UNIT LETTER I , 1650 FEET FROM THE SOUTH LINE AND 330 FEET FROM THE EAST LINE, SECTION 7 TOWNSHIP 18 S RANGE 35 E N.M.P.M.		10. Field and Pool, or Willcut Mid-Vacuum Dev.
15. Elevation (Show whether DF, RT, GR, etc.)		12. County LEA

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE OR RESUME OPER.	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Spotted a 25 Sx. Cement Plug from 7190' - 6940'.
2. Spotted a 25 Sx. Cement Plug at 5-1/2" casing stub at 5940' (50' in and 50' out of 8-5/8" Shoe).
3. Spotted a 25 Sx. Cement Plug from 4875'-4775' (50' in and 50' out of 8-5/8" Shoe).
4. Spotted a 50 Sx. Cement Plug from 915'-815' at 8-5/8" casing stub.
5. Spotted a 50 Sx. Cement plug from 360'-310' at base of 13-3/8" Shoe.
6. Spotted a 10 Sx. Cement Plug at surface with marker.
7. Hole was loaded with mud laden fluids.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Original Signed By

C. L. WADE

SIGNED

TITLE **AREA SUPERINTENDENT**

DATE **May 13, 1970**

APPROVED BY

John W. Runyan

TITLE **Geologist**

DATE **DEC 6 1970**

CONDITION OF APPROVAL, IF ANY: