

NUMBER OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
TRANSPORTER	OIL
	GAS
PRODUCTION OFFICE	
OPERATOR	

## NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

## MISCELLANEOUS NOTICES

strict Office, Oil Conservation Commission, before the work specified is to begin. A copy will be submitted to the Bureau on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Notice by Checking Below

NOTICE OF INTENTION TO CHANGE PLANS		NOTICE OF INTENTION TO TEMPORARILY ABANDON WELL		NOTICE OF INTENTION TO DRILL DEEPER	
NOTICE OF INTENTION TO PLUG WELL	<input checked="" type="checkbox"/>	NOTICE OF INTENTION TO PLUG BACK		NOTICE OF INTENTION TO SET LINER	
NOTICE OF INTENTION TO SQUEEZE		NOTICE OF INTENTION TO ACIDIZE		NOTICE OF INTENTION TO SHOOT (Nitro)	
NOTICE OF INTENTION TO GUN PERFORATE		NOTICE OF INTENTION (OTHER)		NOTICE OF INTENTION (OTHER)	

OIL CONSERVATION COMMISSION  
SANTA FE, NEW MEXICO

Hobbs, New Mexico

June 26, 1964

(Place)

(Date)

Gentlemen:

Following is a Notice of Intention to do certain work as described below at the.....

**Gulf Oil Corporation** **Lee State "EA" (NCT-A)** Well No. **2** in **F**  
 (Company or Operator)  
**SE/** **NW** **13** **18-S** **16-1** **Wildcat** (Unit)  
 (40-acre subdivision) **Lee** **13** **18-S** **16-1** **Wildcat** Pool  
 County.

FULL DETAILS OF PROPOSED PLAN OF WORK  
(FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS)

Drilled to TD 9982'. No show of oil or gas. Propose to plug and abandon as follows:

1. Out 9-5/8" casing at approximately 2900' and recover.
2. 25 sack cement plug across Devonian at 9960'.
3. 25 sack cement plug across Wolfcamp and Penn Detrital at 9000'
4. 25 sack cement plug across Bone Spring at 7820'.
5. 25 sack cement plug across Del. at 5720'.
6. 25 sack cement plug across 9-5/8" shoe at 5000'
7. 25 sack cement plug across 9-5/8" casing stub at approximately 2900'.
8. 25 sack cement plug across Rustler at 1750'.
9. 25 Sack cement plug across 13-3/8" casing shoe at 430'.
10. 50' (10 sacks) cement plug from surface.
11. Clean location and install dry hole marker.

Approved....., 19.....  
Except as follows:Approved  
OIL CONSERVATION COMMISSIONBy.....  
Title.....

Gulf Oil Corporation

Company or Operator

By.....C. D. BORLAND.....

Position.....Area Production Manager.....

Send Communications regarding well to:

Name.....Gulf Oil Corporation.....

Address.....Box 670, Hobbs, New Mexico.....