STATE OF NEW MEXICO ENERGY AND MINEPALS DEPARTMENT

(0-16 81661463	T	
DISTRIBUTION	Ī	i
SANTA PE		
IILE		
U.3.0.1.		
LAND OFFICE		
OPERATOR	7	

OIL CONSERVATION DIVISION

DISTRIBUTION	P O. BOX 2088	Form C-103
SANTA PE	SANTA FE, NEW MEXICO 87501	Sevised 19-1
/ILE	SWITK : 12, WEW MEXICO 87501	
U.3.0.1,		Sa. Indicate Type of Loise
LAND OFFICE		State X Fac
OPERATOR		5. State Cit & Gas Leane No.
		B-1113
	NOTICES AND REPORTS ON WELLS OSALS TO ENGLE OF TO DEEPLY ON PUBL SACE TO A DIFFERENT RESERVOIR. OF FOR PLRAIT TO LOSS CHOOLE OF FUEL PROPOSTALA.	

SUNDRY NOTICES AND REPORTS ON WELLS TOO HOT USE THIS FORM FOR PROPOSALS TO THIS ON PINE OF PUBLISHED AGENTS A DIFFERENT RESERVOIR.	· [X] Faa [
SUNDRY NOTICES AND REPORTS ON WELLS 100 HOT USE THIS FORM FOR PROFISALS TO THIS OR TO BEEN A OF PUBL SACE TO DIFFERENT RESERVOIR. 1. USE "ASSCICATION FOR PIRMIT - " FORM CHOILER FOR PROFISACE TO PROFISACE."	Ch & Gas Leade No.
USE "ASSELICATION FOR PIRMIT -" IFOSM GENDLE OR SUCH PROGRAMMS. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	113
OIL X GAS OTHER-	
\(\daggregar = \d	Agreement Name
	or Lease Name
	n State A/C 2
P. O. Box 2409 Hobbs, NM 88240	
1. (1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.	12 d and Pool, or Wildcat
D 560	uum-Glorieta
THE North LINE, SECTION 6 TOWNSHIP 18S MANGE 35E	
15. Elevation (Show tehether DF, RT, GR, etc.) 12. County 3984 GR, 3996 KB	· Villilli
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:	
SUBSEQUENT REPOR	T OF:
PERFORM REMIDIAL WORK	ALTERING CASING
TEMPOPATILY ABANDON COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT
FILL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JOB	
OTHER	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated works SEE RULE 1103.	late of starting any propose
On 12-13-84 rigged up pulling unit and pulled out of the hole with the rods as stalled the BOP's and pulled out of the hole with the tubing. Went in the hole RTTS packer on 2 3/8" tubing. Set the packer at 5933' and rigged up Hallibur the Glorieta zone (5996' - 6150' perfs.) with 4750 gallons of 15% HCl using 10 diverting material. The average pressure was 2630 psi and the average rate was on vacuum. Had good ball action. Released the RTTS packer and pulled out Went in the hole with the 2 3/8" production string. Landed the seating nipple went in the hole with a 2" x 1 1/4" x 16' pump on 3/4" steel and 1" fiberglass	le with a 4½" ton and treated 08 balls for was 7 BPM. ISIP t of the hole.
the well pumping to the battery.	

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. Steven A. Pohler/ Hoven C. Pohlerine Production Engineer	12 17 0/
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT SUPERVISOR	DEC 2 1 1984